

switch which is mounted on the slider at the end of cut off stroke. Fault detection is performed by counting the number of steps taken to back off the cut off tool and compare the count with the number of steps it takes to reach the limit switch.

#### **6.4.7 Part separator**

During the machine operation, three types of metal pieces fall from the chuck. One is the chip from machining operation and the other two are the desired part and the ejected stub. The chip can be separated out using a grill arrangement. A rail was mounted on the cross slide to catch the desired part when the cut off is complete and channel the part to one bucket. This rail will not catch the stub because when the part is being ejected, the cross slide is at the full out position. In this case, the stub will fall to the catch area for the chips and removed at every cutting tool change.

#### **6.4.8 Stopper**

The function of the stopper is to position the raw material in the axis of lathe's rotation. The stopper must operate while the chuck and raw material are rotating at 1040 rpm. The stopper must also have three stopping position. One near the off tool to position material for end cut off for new raw material, one at the position where the chuck will clamp the material for machining operation, and one out of the way when machining begins. Of these, three position, only the position for material clamping must be held to the tolerance of  $\pm 0.15$  mm. This position control the length of the finished part. The stopper will be adapted from the lathe's tail stock. The screw of the tail stock will be driven by stepper motor for precise positioning. With the pitch of the tail stock screw being 16.0 mm per revolution and the stepper resolution is 200 steps per revolution, the positioning resolution is  $16.0 / 200 = 0.08$  mm. This resolution is well within the 0.15 mm required by part length tolerance. The drive for this application is not critical and the existing hybrid type Step-Syn motor type 80 two phase motor number 103-815-2 was tested with satisfactory result. This motor has holding torque of 21.6 kg-cm and running torque of 12 kg-cm for immediate start-stop operation at 60 rpm (200 steps per second). The fault detection method and the control method for the stopper is the same as the cross slide.

#### **6.4.9 Controller**

It can be seen later on in this document that in order to meet the cycle time of 40 seconds per piece, several things has to happen at the same time as well as the precise control of the stepper motor step rate and number of steps taken. Further more, fault detection of the machine must also be active at the same time. These requirements cannot be easily met with standard programmable logic controller (PLC) and microprocessor system must be used for the control purpose. The microprocessor selected for this application is the microprocessor designed specifically for control application manufactured by Intel. It is in the MCS 51 family which is particularly suitable for control purpose. The complete microprocessor board is manufactured in Thailand by Sila Research Inc. and this would guarantee spare part availability. The software for the controller is written in assembly language and embedded in the controller board using erasable programmable read only memory (EPROM) and the entire microprocessor board contain no moving part. The controller communicate with use via switches and lamps. A set of part dimension trim control is built in so that tool setting is not required when adjustment is necessary. More detail on the controller will be discussed in another section of this document.

## 7. STEP MOTOR DRIVE

Step motor used in this project is a hybrid type with four phases. The characteristic of step motor is that it can be moved in small steps (usually 200 steps per revolution) and capable of sudden start and stop operation. The speed of the stepper motor can be controlled by the frequency of phase excitation and the direction of rotation is controlled by the sequence of phase excitation. A step motor can be driven in one of three ways. Single phase excitation provide lowest power consumption and heat generation. Two step drive provide high operating torque. Two-one phase drive provide halve step motion. In general, two phase drive is used except for positioning of the turning tool on the cross slide which require two-one phase drive to meet the positioning resolution requirement. Step motors are rated according to it's holding torque, phase current, and phase voltage. Torque-speed curve is supplied in the motors catalog.

The power supply for the stepper motor is usually of a voltage higher than the motor rating and the voltage to the motor is reduced by a set of series resistor. With this arrangement, torque at high step rate is improved due to better resistor - inductor ratio. Common supply voltage recommended by the factory is 24 volts but in practice, 13.8 volt supply is much more common and is selected for this system. The value of series resistor is calculated using the following equation:

$$R_s = R_m(V_s - V_q)/V_m - R_m$$

Where  $R_s$  = value of series resistor in ohm  
 $R_m$  = phase resistance of stepper motor  
 $V_s$  = supply voltage  
 $V_q$  = voltage drop across drive transistor  
 $V_m$  = motor voltage rating

Supply voltage of 13.8 volt is used because of availability. The voltage drop across the drive transistor is the saturation voltage which is normally about 0.8 volt. The power rating of the series resistor can be calculated from the equation:

$$P_s = I_m^2 R_s$$

Where  $P_s$  = power rating of series resistor in watt  
 $I_m$  = current rating of the motor

It is common that the power rating of series resistor is in the order of 20 to 60 watts and the resistors used are commercially available adjustable power resistor with rating of 100 watt. The power dissipated by the resistor is quite large and cooling fan is required.

## **8 THE CONTROLLER**

### **8.1 Function of Controller**

As the name imply, a controller is used to control a process which in this case is the single purpose lathe. The controller monitor external events (called inputs) and base on those events, give commands to external actuators (called outputs). Inputs to the controller is user activated switches or switches that indicate position of drive systems. The outputs of this system compose of step motors, pneumatic actuator, hydraulic actuators, and indicator lamps. The control process will act according to pre programmed steps required by the process. These pre-programmed steps will be called operation chart. The description of the operation chart follows:

### **8.2 Operation Chart**

The operation chart is a chart that shows when each of the system components need to be activated and for how long. For the single purpose lathe, there are 6 actuator involve which are the linear feeder, rotary feeder, chuck jaw, cross slide, turning slide, and stopper. Description of each of these components can be found in the 'Configuration' section. The chart has the time as the horizontal axis and actuator speed as the vertical axis. This chart is created to aid the programming process and do not show the conventional actuator displacement. The chart show 7 separate fields of action to process the raw into finished part. The description of each field follows:

The first field show actions required to feed the part. This involve pulling the linear feeder back, feeding part from the hopper via rotary feeder on to the rail, and pushing the part through the chuck opening. Before the part can be fed through the chuck opening, the stopper must move to the position just outside of the chuck opening and the turning tool move in to cutting position.

The second field is used to cut the face off a new raw material before part production begin. During this process, the turning tool will smooth out the side of the part before cutting it off. This is required because the raw material is cast iron with rough finish and cutting it directly with the cut off tool may cause tool breakage. While the turning tool is operating, the stopper begin to move back to prepare for next operation. When the turning process is finished, the cut off tool will move in to cut the face of the new material. After that, the cut off tool will move back to allow the material to be fed for further machining.


The last five fields are identical. For each of these field, one finished part will be produced. The process begin by turning operation followed by cut off operation. After the cut off operation is finished, the cut off tool is retracted, the stopper move in place, and the new material is fed by unclamping the chuck jaw while the material is being pushed by the linear feeder. After the material is in place, the chuck jaw clamps the new material and the next field of operation can begin.

### **8.3 Controller Board Configuration**

The heart of the control unit is a microprocessor board selected from local manufacturer to guarantee spare part availability. The board used is ANT-32 made by Sila Research Inc. This particular microprocessor board use Intel 8032 as the microprocessor and two 8255

programmable peripheral interface (PPI) for input and output operation. This configuration allow up to 48 bits of input/output plus another 8 bits from the CPU port (P1.0 through P1.7). The board is configured with RS-232 communication link for future expansion and watch dog timer for automatic reset in case the CPU is locked up for any reason. Up to 32K of code memory can be programmed using EPROM. This particular company also produce several external boards such as stepper motor driver and relay boards which can be connected to the CPU board with supplied connecting cable.

# OPERATION CHART



Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 File: SUDE17  
 Designed by: Thawon  
 Date: 28 Oct 96  
 Scale: 1mm=1sec  
 Drawing No. 7

## 8.4 Inputs and Outputs Configuration

The single purpose lathe require several input and output for it to function properly. According to Sila convention. The First PPI is designated as U1 and the second PPI designated as U2 while the letter U stands for user port. For each user port there are three separate 8 bit ports called A, B, and C according to Intel convention. The I/O configuration list follows:


| PORT | I/O | ACTIVE | DESCRIPTION                    |
|------|-----|--------|--------------------------------|
| U1A0 | O   | LOW    | MOTOR 0 (CUT) PHASE A          |
| U1A1 | O   | LOW    | MOTOR 0 (CUT) PHASE B          |
| U1A2 | O   | LOW    | MOTOR 0 (CUT) PHASE C          |
| U1A3 | O   | LOW    | MOTOR 0 (CUT) PHASE D          |
| U1A4 | O   | LOW    | MOTOR 1 (TURN) PHASE A         |
| U1A5 | O   | LOW    | MOTOR 1 (TURN) PHASE B         |
| U1A6 | O   | LOW    | MOTOR 1 (TURN) PHASE C         |
| U1A7 | O   | LOW    | MOTOR 1 (TURN) PHASE D         |
| U1B0 | O   | HIGH   | STEPPER MOTOR POWER SUPPLY     |
| U1B1 | O   | HIGH   | ROTARY FEEDER MOTOR ACTIVATION |
| U1B2 | O   | HIGH   | LINEAR FEEDER BACK             |
| U1B3 | O   | HIGH   | LINEAR FEEDER FORWARD          |
| U1B4 | O   | HIGH   | CHUCK CONTROL                  |
| U1B5 | O   | HIGH   | HYDRAULIC PUMP POWER           |
| U1B6 | O   | HIGH   | LATHE POWER CONTROL            |
| U1B7 | O   | HIGH   | READY LAMP                     |
| U1C0 | I   | HIGH   | HOPPER EMPTY SWITCH            |
| U1C1 | I   | LOW    | LINEAR FEEDER FULL IN SWITCH   |
| U1C2 | I   | LOW    | LINEAR FEEDER STUB SWITCH      |
| U1C3 | I   | LOW    | TURNING SLIDE HOME SWITCH      |
| U1C4 | I   | LOW    | CUT OFF SLIDE HOME SWITCH      |
| U1C7 | I   | LOW    | SPARE                          |
| U2A0 | O   | LOW    | MOTOR 2 (STOPPER) PHASE A      |
| U2A1 | O   | LOW    | MOTOR 2 (STOPPER) PHASE B      |
| U2A2 | O   | LOW    | MOTOR 2 (STOPPER) PHASE C      |
| U2A3 | O   | LOW    | MOTOR 2 (STOPPER) PHASE D      |
| U2A4 | O   | HIGH   | HOPPER EMPTY LAMP              |
| U2A5 | O   | HIGH   | REMOTE ALARM                   |
| U2A6 | O   | HIGH   | SPARE                          |
| U2A7 | O   | HIGH   | SPARE                          |
| U2B0 | I   | LOW    | DIAMETER TRIM BIT 0            |
| U2B1 | I   | LOW    | DIAMETER TRIM BIT 1            |
| U2B2 | I   | LOW    | DIAMETER TRIM BIT 2            |
| U2B3 | I   | LOW    | DIAMETER TRIM BIT 3            |
| U2B4 | I   | LOW    | LENGTH TRIM BIT 0              |
| U2B5 | I   | LOW    | LENGTH TRIM BIT 1              |
| U2B6 | I   | LOW    | LENGTH TRIM BIT 2              |
| U2B7 | I   | LOW    | LENGTH TRIM BIT 3              |
| U2C0 | I   | LOW    | TEST CODE BIT 0                |
| U2C1 | I   | LOW    | TEST CODE BIT 1                |
| U2C2 | I   | LOW    | TEST CODE BIT 2                |
| U2C3 | I   | LOW    | TEST CODE BIT 3                |
| U2C4 | I   | LOW    | GO SWITCH                      |
| U2C5 | I   | LOW    | STOP SWITCH                    |
| U2C6 | I   | LOW    | EMERGENCY STOP SWITCH          |
| U2C7 | I   | LOW    | SPARE                          |

## 8.5 Watch Dog Timer

In industrial control application, it is quite possible despite all the precautions exercised during design stage, that the CPU will lock up or get lost during its operation. This may be due to improper hardware/software design, power surge, brown out of line power, intense electromagnetic radiation, sun spot activity, or whatever reason. When that happens, the hardware connected to the controller is out of control. The hardware could be the lathe motor which is rated at 3 hp. and sometime things can get dangerous. To prevent this problem, an electronic circuit is designed to cope with this kind of events. The circuit under discussion is called 'watch dog timer'. The timer will have to be activated (petted?) once every second to keep it happy. If the activation signal does not come regularly, it means that the CPU is not doing what it supposed to do and the watch dog timer will proceed to reset the CPU. Once reset, a good practice in controller programming is to have the CPU wait for a push button switch before it continues to work. The watch dog timer, in this case, is activated by complimenting the P1.7 bit regularly in the program loop.

## 8.6 Driving Multiple Step Motors

Looking at the operation chart, it can be seen that more than step motor need to work at the same time at different step rate and number of steps. The step motor used in this project is a four phase type. To make the motor turn, the phases must be exited in sequence. The step rate can be as high as 300 steps per second which means that the CPU must issue a command to the step motor driver 300 times in one second. If only one step motor is in operation at any given time, a simple software timing loop can be utilized to drive the motor. In this case, more than one step motor is working at the same time and while the motors are being operated, other control function is also required. A software loop for such operation would be hopelessly complex and the accuracy of motor speed is questionable. The approach taken in this project is to use the internal timer available in the CPU to operate the stepper motor in the background while other control function is being operated on in the foreground. In fact, two timers are operated simultaneously in the background so that the motors can run at different speed. The timer for MCS-51 family microprocessor runs at 1/12 crystal speed and it operates as a counter counting number of pulses from the crystal divided by twelve. When the timer reaches the maximum value of FFFFh (65535) it will roll over to 0000h and at the same time generate an interrupt to the CPU if the interrupt enable register is properly programmed. When the CPU is interrupted, it will call the interrupt service subroutine and this interrupt service routine is used to issue commands to the stepper motor controller. To set the step rate of the motor, the timer register will be loaded with a value larger than zero during the interrupt service. This will make the timer fill up faster and hence increase the step rate. The value to load in to timer register can be calculated from the following equation:



$$\text{Reload value} = \text{round}(\text{FFFFh} - f / (12 * S) - T_o)$$

where  $f$  = Crystal frequency = 11,059,200 Hz

$S$  = Step rate of motor (Hz)

$T_o$  = Overhead time for reload operation (cycles) = 5

The two timers used to operate the stepper motor are assigned the same priority level so that when an interrupt is requested while the other is in progress, there will be slight delay for the first one to finish before the second routine can be executed. This causes minor speed variation of the stepper motor when two motors are being operated simultaneously.

### 8.7 Error Detection of Step Motor Drive

When using a step motor as a drive unit, it operates in an open loop mode. What this means is that, when the motor is overloaded, it skip steps and the actual displacement of the actuator is not what has been programmed. This step skipping cannot be detected because no feed back information is available. The step skipping can be caused by the following events:

- The step motor is driven at excessively high step rate.
- High friction due to lack of lubrication of the slide.
- High friction due to improper adjustment of slide.
- Excessive force due to broken cutting tool insert.
- The tool is stalled because the chuck is not turning.
- Insufficient voltage is available to drive circuit.

Whatever the cause, the parts produced will most likely not be in proper tolerance and the condition must be corrected. It is not possible to detect the problem when the motor is in forward motion but when the motor reverse the direction to return to reference position (detected with limit switch) the number of backward steps can be counted and compare to the number of forward steps taken. If the two counts are differ more than a pre specified amount, skipping of steps has occurred and the operation will stop and the error indicator lamp will come on. Please note that the number of step count for the forward motion and backward motion will never be the same because the on and off position of the limit switch is not at the same position. Backlashes in the drive mechanism also contribute to this difference

To detect the reference position properly, the step count is monitored only after the switch contact has made the transition between on and off. If the limit switch malfunction, the motor can step forward forever or until something break. This condition can be prevented by programming in the maximum number of steps expected for limit switch stroke. If the number of steps exceed a pre specified value, it can be concluded that the limit switch has failed and the error lamp will come on.

### 8.8 Error Detection of Pneumatic Drive

The control unit is interfaced with the pneumatic system with a solenoid valve. When the valve is operated, the compressed air will rush in to the cylinder and cause the piston to move and perform the required task. The pneumatic actuator may not be able to perform it's task in the following circumstances:

- The supply air pressure is low or absent.
- The solenoid valve is stuck.
- Open circuitry between controller and valve.
- Air line is leaking.
- Mechanical binding of actuator.

The air cylinder is equipped with two reed switches. The reed switch is activated by magnetic material embedded in the piston and can detect the piston positions. The check of pneumatic device function is done by issuing a command for it to move and then monitor if the appropriate reed switch is activated within a specified time frame. If the reed switch is not activated properly, the operation stop, and the error lamp comes on.

### **8.9 Controller Software**

The controller software is written in assembly language for speed and compactness. The software is tested on the actual machine using EPROM emulator. The final version of the software is programmed in to an EPROM and inserted in to the code memory socket of the micro controller board.

### **8.10 Controller Housing**

The controller unit which include the CPU board, stepper motor drivers, relay boards, input board, and CPU power supply is housed in a personal computer housing. The housing is equipped with cooling fan and air filter to cope with the production line environment. The fan and filter system is designed such that the interior of the housing contains positive pressure when operating to keep out the dust and other contaminants. The stepper motor resistor pack and power relays are housed in a separate box to prevent excessive heat built up and electrical noise that could upset the CPU board.

## **9 TEST FUNCTIONS**

The control system is designed with a rotary switch to enable individual testing of components of the single purpose lathe. This would allow easy maintenance, testing, trouble shooting, and adjustment of the lathe. Each of the switch position is discussed in turn:

### **9.1 Position 0: Normal Operation**

This is the normal run position of the lathe. The switch is kept at this position during normal operation.

### **9.2 Position 1: Single Piece Test**

This is the single piece position. When this function is selected, the lathe will machine the part one at a time and then stop. The cycle repeat itself when the go switch is pressed. This function is used for quality control and tool setting. The part diameter and length can be adjusted using trim switches on the control unit.

### **9.3 Position 2: Turn Slide Test**

This function is for turning slide test. After this function is selected, the go switch need to be pressed to initiate the test. The turning slide will move to the end of stroke. At this position,

the tip of the turning tool should be about 0.5 mm behind the edge of the cut off tool on the chuck side. When the go switch is pressed again, the turning tool will retract to full back position. This position should be about 26.5 mm from the edge of the cutting tool on the tail stock side. These positions can be adjusted by moving limit switches or limit switch actuator if applicable.

#### **9.4 Position 3: Cross Slide Test**

This function test the cross slide positioning mechanism. The cross slide has three critical positions. The first is against the limit switch which is the end of cut off position. The second is the turning position. The third is where cut off tool is about to make contact with raw material. For each time that the go switch is pressed, the cross slide will sequence through these positions in turn. The turning position can be adjusted by moving the limit switch and then fine tune with trim switch in the controller. The raw material contact switch is adjusted by moving the cut off tool in its holder with a part 21.30 mm diameter clamped in the chuck.

#### **9.5 Position 4: Stopper Test**

This position is used to adjust the tail stock position. When the go switch is pressed each time, the stopper will sequence between the full back position, halve way position, and full out position. The critical position for the stopper is the halve way position which control the finished part length. This position can be adjust by loosen the tail stock lock, install cylinder rod in the chuck so that the end of the rod is exactly 26.0 mm from the cut off tool edge on the tail stock side, and then operate the go switch. At this point, the step motor will push the stopper to halve way position. Since the tail stock is not locked, the entire tail stock structure will be pushed back to the appropriate position. The tail stock then can be locked in to place against the lathe bed. The trim adjustment in the control box can then be adjusted for fine tuning of the position.

#### **9.6 Position 5: Linear Feeder Test**

Position 5 is used to test the operation of the linear feeder. Pressing the go switch once in this test position will cause the linear feeder to go to full back position. At this position, the tip of the linear feeder should be cleared of the feeding rail at the rotary feeder. The position is not critical. Pressing the go switch again will cause the linear feeder to move to full out position. At the full out position, the tip of the linear feeder should be level with the chuck jaw. The stroke of the linear feeder is not adjustable and this test is provided for testing during fabrication and alignment of the feeder system.

#### **9.7 Position 6: Rotary Feeder Test**

This function is used to test the hopper and rotary feeder. Pressing the go switch once at this test position will cause the rotary feeder to feed one part in to the linear feeder rail.

#### **9.8 Position 7: Chuck Test**

This position is used to test the chuck operation. Pressing the go switch once will cause the chuck to open and pressing the switch again will cause the chuck to close. In the full open position, the chuck jaws should just be able to accommodate a 26 mm diameter cylinder.

## **9.9 Position 8: Lathe Motor Control**

This function will test the on/off function of the lathe motor control.

## **10 ERROR CODES**

The error code is displayed on a 20 characters liquid crystal display (LCD) module mounted on the front panel of the control unit. Normally, the error display is off and when the control unit detect any error in the machine operation, the error display will show a short error message corresponding to the type of error that occur. During an error condition, the lathe motor and the hydraulic power unit will be turned off and the red alarm lamp as well as the remote alarm contact will be on. This section describe possible error associate with each error code and methods to test and fix the problem.

### **10.1 ERROR CODE 01 CROSS LIMIT**

This error occur when the cross slide attempt to leave the home position. Initially, the contact of the limit switch attached to the cross slide is in close position and as the step motor turn the drive screw to move the cross slide, the switch will be released. If the switch is not released after a fixed number of steps, the error condition is detected. This error is caused by one of two things. One is the drive system malfunction and the other is the limit switch malfunction.

#### **10.1.1 Drive Malfunction**

The drive system malfunction can be caused by the following:

##### **10.1.1.1 Loose coupling**

The step motor drive action create quite a bit of torsional vibration in the related parts which can cause the set screw in the coupling to work itself loose. To check this, turn the coupling by hand and see if the associated slide move and some resistance is felt from the drive motor. If the slide does not move, the set screw on the slide side is loose. If the resistance of the step motor is not felt, the set screw on the motor side is loose. The set screw is assembled using Permatex thread lock compound, and if it was disassembled, the compound will have to be replaced. To do this, remove the lock screw using an allen wrench (L shaped wrench with hexagonal cross section) and clean it with wire brush. Put a drop of thread lock compound on the screw thread and tighten the screw.

##### **10.1.1.2 Excessive slide friction**

Excessive slide friction can be caused by improper adjustment of the slide clearance or lack of lubrication. Lubricate and adjust the slide according to lathe manufacture recommendation.

##### **10.1.1.3 Drive motor malfunction**

The drive motor function can be tested by moving test selector switch to position 2 and press the go switch. Pressing the go switch will cause the slide to alternately move forward and backward. If the motor do not turn smoothly, check the following:

- a) The 12V DC power supply should have output of 12.5V or more while the drive motor is running. If the supply voltage is below this, replace the power supply.
- b) The resistance of the resistor pack should be about 2.5 ohm. If the resistance is much higher than 3 ohm, replace the resistor pack.
- c) Try replacing the CPU to stepper motor driver cable.
- d) Try replacing the stepper driver board making sure that the jumpers are at the same positions for replacement board.

#### **10.1.2 Limit Switch Malfunction**

The limit switch can malfunction when operated with oil or water contamination. The following procedure will check out the limit switch operation.

- a) With the controller power on, turn the coupling so that the slide move away from the limit switch in question.
- b) Check the voltage across the limit switch terminal. With the switch released, the voltage should be  $5V \pm 0.5V$ . If the voltage is below the specified value, disconnect the wiring at limit switch and check switch resistance. Replace the limit switch if the resistance is not infinite.
- c) Press the switch in, the voltage across the switch should be zero. If not, replace the switch.
- d) With the switch pressed, the voltage across the switch connection terminals in the control box should be less than 0.1 V. If the voltage is higher than this, replace the switch wiring.
- e) If the switch system pass all the tests and the system is still not operating correctly, try checking the voltage level at the 8255 PPI on the CPU board while operating the switch. If the voltage level change between 4.5 V and 0.2 V, replace the 8255 chip.
- f) After the tests, if the system still have problem, consult the software listing and change the appropriate hardware parameters. The problem may be caused by increase in backlash after long period of use.

#### **10.2 ERROR CODE 02 CROSS STROKE**

This error can occur when the cross slide return to home position and it take too few steps for the motor to accomplish this. The most likely cause for this error is the broken cutting tool. When the cutting tool is broken, the force required be drive mechanism is excessive and may cause the drive motor to skip steps which cause the number of steps backward to be less than the number of steps required to move forward.

#### **10.3 ERROR CODE 03 CROSS NOT RET**

This error occur when the cross slide return to home position and it take too many steps for the motor to accomplish this. The diagnostic procedure is the same as error code 1. If all

else fail, try to change step rate for tool movement in the software. Lower step rate will yield more motor torque and should remedy the problem.

#### **10.4 ERROR CODE 04 TURN LIMIT**

The error code 4 occur when the turning slide attempt to leave the home position but did not succeed. The diagnostic is the same as error code 1.

#### **10.5 ERROR CODE 05 TURN STROKE**

This error occur when the cross slide return to home position and it takes too few steps for the motor to accomplish this. The remedy is the same as error code 3.

#### **10.6 ERROR CODE 06 TURN NOT RET**

This error occur when the cross slide return to home position and it takes too many steps for the motor to accomplish this. The remedy is the same as error code 2.

#### **10.7 ERROR CODE 07 STOPPER LIMIT**

This code is associated with stopper drive. Look for mechanical binding and if non is found, try to trouble shoot the problem with procedure associated with error code 1.

#### **10.8 ERROR CODE 08 STOP STROKE**

This error occur when the stopper return to home position and it take too few steps for the motor to accomplish this. The remedy is the same as error code 3.

#### **10.9 ERROR CODE 09 STOP NOT RET**

This error occur when the stopper attempt to return to home position and failed.

#### **10.10 ERROR CODE 10 CHUCK NOT CLR**

This error could occur during lathe initialization when the liner feeder is operated and cannot reach it's full out position. This is caused by a piece of raw material which is still in the chuck when the lathe is turned on. Remove the raw material from the chuck and try again.

#### **10.11 ERROR CODE 11 LINEAR NOT RE**

This error code deal with linear feeder. The error is generated when a command is issued to the linear feeder and the reed switch mounted on the cylinder is not closed in a specified amount of time. This error is caused by:

- a) Mechanical deformation of cylinder/shaft.
- b) Binding of mechanical parts.
- c) Air supply pressure is below 4 bar.
- d) Pressure regulator is not properly adjusted.
- e) Speed control valve is not properly adjusted.
- f) Air leak in the system.
- g) Reed switch malfunction.

- h) Defective solenoid valve.
- i) Defective drive relay.
- j) Defective 24 VDC supply.

#### **10.12 ERROR CODE 12 ROTARY PROB.**

This error code is associated with rotary feeder malfunction. When the rotary feeder is operated and the linear feeder detect no raw material in the chuck, this error is generated.

#### **10.13 ERROR CODE 13 HOPPER EMPTY**

This error code is generated when the limit switch at the part hopper detect hopper empty condition

#### **10.14 ERROR CODE 14 EMERGENCY ST**

This error condition is generated when the lathe is stopped abnormally by pressing the emergency stop button.

#### **10.15 ERROR CODE 15 STOPPED**

This code is generated when the stop button is pressed. When this button is pressed, the lathe finish the piece of raw material before stopping.

#### **10.16 ERROR CODE 16 COUNT ERROR**

This error is generated when the lathe have machined five sliders from the raw material and the stub of the piece is not found by the stub detection switch. This error occur when the stopper setting is incorrect or the raw material is abnormally long.

### **11 HARDWARE PARAMETERS IN THE CONTROL SOFTWARE:**

#### **11.1 Overview**

The program for the single purpose lathe is written in assembly language. This program must be translated in to machine code using a program called assembler and then written to a permanent memory called erasable programmable read only memory (EPROM). The EPROM is then plugged in to the microprocessor board of the single purpose lathe. The program contain hardware parameters which can be changed by the user to suit the production requirements. The hardware parameters include cut speed, move speed, forward stroke and reverse stroke of sliders. Changing these parameter is analogous to changing the setting of flow control valves and limit switch positions of hydraulically operated machines.

#### **11.2 User Tool Kit**

To enable the user to change the hardware parameter to suit the production requirement, a tool kit has been supplied for this purpose. The tool kit contain the following parts:

1. Lined suitcase to contain all the parts.
2. One master disk (3.5" IBM format) containing programs.
3. One work disk (3.5" IBM format) containing programs.

4. One EPROM programmer with power adapter.
5. One RS-232 cable for 9 pins connector.
6. One RS-232 cable for 25 pins connectors.
7. One EEPROM for program testing.
8. Three EPROM for working program.
9. Ten opaque stickers for EPROM software protection.
10. This document translated in to Thai.

Each of the tool kit parts will be discussed in turn in the following paragraphs:

#### **11.2.1 Suitcase**

The suitcase is a hard shelled suitcase lined with open cell foam rubber to protect the internal parts from shock, vibration, moisture, and temperature variations. The suitcase contain magnetic recording material and is not shielded against magnetic field. The suitcase should not be stored near strong magnetic field such as power transformers, speaker enclosures, or uninterruptable power supplies.

#### **11.2.2 Master disk**

The master disk is packed along with the work disk in a plastic container wrapped with aluminum foil to protect it from x-ray radiation at the airport while being transported from Chiang Mai. The master disk contain the original lathe control software listing as will as machine code in Intel hexadecimal format. It also contain operating system, editor, assembler, and communication software needed for changing hardware parameters. The disk is write protected and should be kept that way.

#### **11.2.3 Work disk**

The work disk is an identical copy of the master disk but is not write protected. It is used for making program modifications and if it become defective, another copy can be made from the master disk.

#### **11.2.4 EPROM programmer**

The EPROM programmer is an electronic device that take machine code from a microcomputer via series communication line and then write corresponding bit pattern in to an EPROM. Once the information is written, it is permanent and can only be erased by expose the EPROM to strong ultraviolet radiation for some amount of time depending on the light intensity.

#### **11.2.5 RS-232 cable**

The RS-232 cable is used to transfer information from a personal computer to the EPROM programmer. There are two standard type of connectors in use. One use 9 pin connector and the other use 25 pin connector. One cable is supplied for each type of connector.

#### **11.2.6 EEPROM**

One EEPROM is supplied in the kit for program testing. EEPROM is an abbreviation of electrically erasable programmable read only memory. The EEPROM is suitable for program

testing because it can be written many times by EPROM programmer without having to be erased first by ultraviolet light. This feature aid program testing but the information contained inside can be erased by power surge in the system and is not as rugged as the EPROM counter part. It is not advisable to use EEPROM to store program code in the microprocessor board for extended use.

#### **11.2.7 EPROM**

The EPROM is used to store program code the controller board. The EPROM can be written only once by the programmer. If it is desirable to rewrite an EPROM, it must be erased first by ultraviolet light through the crystal window on the chip. Once the EPROM is written, it should be protected from light by placing an opaque sticker on the crystal window.

#### **11.2.8 Opaque sticker**

The supplied opaque sticker is used to protect the code in the EPROM from being erased. The sticker should be place on the EPROM chip and cover the entire transparent window on the chip. Material like masking tape or paper sticker is not truly opaque and should not be used. Black electrical insulation tape can be used but the glue may run at elevated temperature.

#### **11.2.9 User manual**

The user manual in Thai is translated from part of the English language report. The report may be referred to for clarification.

### **11.3 Relations of Parameters**

The hardware parameter is related to the lathe parameter. Each of the parameters are discussed in turn:

#### **11.3.1 Pitch**

The pitch for each slider is the linear distance that the slide travel when the drive screw is rotated one full revolution. The unit used is in millimeter per revolution.

#### **11.3.2 Forward stroke**

The forward stroke for each slider is the distance that the slider will move measuring from the position that the slide leave limit switch (switch contact begin to open) to the end of the travel required by the operation. Some slider such as the stopper may have several forward strokes.

#### **11.3.3 Reverse stroke**

The reverse stroke is the distance that the screw is expected to turn to bring the slider back in contact with limit switch at the point that the switch contact begin to close. The reverse stroke is longer than forward stroke because it will include backlash in the drive mechanism plus the difference between the position that the switch begin to open and switch begin to close. The closing and opening position of switch contact is always different due to histeresys built in to the switch mechanism.



### 11.3.6 Timer reload value

The step motor speed is controlled by CPU internal timer. The timer normally begin the count at 0 and count up to 65535. When the terminal count is reached, the timer generate an interrupt which cause the CPU to turn the motor one step. At this point the CPU can reload the timer with a value larger than 0 to cause the timer to reach the terminal count earlier. The larger the reload value, the faster the step rate. The timer run at 1/12 of crystal frequency and the equation to calculate the reload value follows:

$$R = 65535 - f/12S - T_o$$

where             $R$  = timer reload value  
                     $f$  = crystal frequency = 11,059,200 Hz  
                     $S$  = step rate (step/second or Hz)  
                     $T_o$  = software overhead to reset timer = 5 cycles

A table for reload value can be found in Appendix A.

### 11.3.7 Step rate

The step rate of the motor correspond to the tool speed required to machine a part. The tool speed is normally referred to as feed rate which has a unit of mm per chuck revolution. The step rate can be calculated from the following equation.

$$S = WFr/(60P)$$

where             $S$  = step rate in Hz  
                     $W$  = chuck speed in rpm.  
                     $F$  = feed in mm/revolution  
                     $r$  = motor resolution in steps/revolution  
                     $P$  = drive screw pitch of slider

Once step rate is calculated, the appropriate reload value can be found on the timer reload table.

The torque-speed characteristic of a stepper motor is such that, when the step rate increase, the torque is reduced. This is the limiting condition for tool speed during tool movement without material removal. If the step rate is too high, the motor will skip steps during tool movement and cause error condition. The optimum tool speed is best determined experimentally since the drive assembly inertia and friction is difficult to calculate.

## 11.4 Constant Definitions

In the program listing under the heading of 'DEFINE HARDWARE PARAMETERS' contain parameters of the machine. These parameters can be changed to effect the way the single purpose lathe operates. The description if each parameter follows:

m0fstroke:

This constant refer to motor number 0 forward stroke. Motor number 0 is associated with the cross slide and the number that follow 'equ' is the number of steps to achieve this stroke. This is the number of steps that the drive motor will move to cut off the part from the raw

material after leaving limit switch. If the cutting tool do not quite reach the center of the part, this number can be increased. If the cutting tool move beyond the center of the part, the number may be decreased.

**m0rstroke:**

This constant is motor number 0 reverse stroke. This is the distance that the cross slide expected to move until it reach the limit switch. If the actual step required to reach switch is much larger than the specified number, it means that the slide is jammed in the reverse stroke and error condition will result. This problem may be caused by excessive friction on the slide or the step rate set to move the tool back is too high. If the motor take too few steps to reach the switch, it means that the slide is jammed in the forward stroke. The condition may be caused by defective cutting tool

**m0tstroke:**

This is the number of steps required for the cross slide to reach turning position. The number is the number of steps that the motor will turn beyond the limit switch position. This number is added to the diameter trim switch on the front panel before the program move the cross slide. At later stage in the lathe development, a micrometer is added to the lathe as the activator for the limit switch to ease the part diameter setting and this variable is no longer used for part diameter setting.

**m0cutrelo:**

This is timer reload value for cutting off the part. This number control cutting speed of the cut off tool. Higher reload value will cause the cut off rate to increase.

**m0movrelo:**

This is timer reload value for moving the cross slide back to limit switch position. If this value is set too high, the motor may skip step and cause error condition. If it is set too low, productivity will suffer.

**m1fstroke:**

The number is the number of steps required for the turning tool to complete the turning operation. The effect of the value setting is similar to m0fstroke.

**m1fstroke1:**

This stroke is used to prepare the turning tool before turning the head of a new part. It is used during facing operation of a new part.

**m1fstroke2:**

This is turning stroke used after the turning tool moved in to position by m1fstroke1. The purpose of this operation is to turn the head of a new part and get ready for facing operation.

**m1rstroke:**

This is the stroke used for returning the cutting tool to home position. The effect of this number is similar to m0rstroke.

**m1cutrelo:**

This is the timer reload value for turning. The effect of this parameter is similar to m0cutrelo.

m1movrelo:

This is the timer reload value for returning the top slide to home position. The effect of the number is similar to m0movrelo

m2fstroke1:

This number is the number of steps required for the stopper to reach normal part stop position. It is referred to in other part of document as stopper position 1. The value from the front panel length trim switch is added to this value before the program start the execution of moving the stopper.

m2rstroke1:

This is the number of steps the stopper expected to move back to limit switch from position 1 described above.

m2fstroke2:

This is the stopper position 2 which is used to stop the raw material near the chuck for facing operation.

m2rstroke2:

This is the number of steps the stopper expected to move back to limit switch from position 2 described above.

m2fstroke3:

This is the stopper position 3 which is used to push the raw material in to the chuck. It is used during self test after power up when the control unit detect raw material in the lathe. This motion assure that the path of the cross slide is clear before testing.

m2rstroke3:

This is the number of steps the stopper expected to move back to limit switch from position 3 described above.

## 11.5 Reprogramming the Lathe

The following instruction is used to reprogram the lathe for different operating parameter. An IBM compatible computer with at least one serial port and one 1.4 Mb disk drive is required for the process

1. Connect the EPROM programmer to COM1 port of the computer using supplied RS-232 cable.
2. Power up the computer.
3. Plug in the EPROM programmer power adapter.
4. Inset the work disk in drive A:
5. Press [Alt][Ctrl][Del] to reset the computer.
6. When A>\_ appear on the screen type edit[Enter]
7. The program listing will appear on the screen. Locate 'DEFINE HARDWARE PARAMETERS' section and make required alteration with arrow keys and backspace key
8. Press [Alt]FS to save the alteration.
9. Press [Alt]FQ to exit editor.
10. The assembler will be started automatically. Look for error message and if there is non, proceed to step 11, otherwise, go back to step 6 to correct the problem.

11. Press SEL key on the EPROM programmer until the green lamp with a number corresponding to EPROM part number is lit.
12. Put a new EPROM in the green zero insertion force (ZIF) socket observing the orientation of the notch on the EPROM chip. Lock the chip securely using the lever on the ZIF socket.
13. Press FUNC key on the programmer until BLK lamp is lit.
14. Press ENT key and observe BLK lamp. If it flash, the EPROM is not blank and cannot be programmed. In this case, replace the EPROM and go back to step 13.
15. Press FUNC key on the programmer until DWL lamp is lit and press ENT.
16. At the computer type send[Enter] to send the machine code from the computer to the programmer.
17. The DWL lamp should flash for a few seconds during the data transfer and then remain on. If the lamp flash after the transfer, the communication line is bad or the serial port is not properly set. This is caused by some computer that do not allow a start up from floppy disk.
18. Press FUNC key until WR lamp is lit and press ENT.
19. If no lamp flash after a few seconds, the EPROM is ready, if a lamp flash, the EPROM selection in step 11 may not be correct.
20. Remove power from the control unit and replace the EPROM.
21. Power up the lathe and test the operation.

For testing of the operation and experimenting with parameters, use the supplied EEPROM and skip step 13 and 14. Replace the EEPROM with EPROM when everything is working right.

## **12. PROBLEMS ENCOUNTERED AND SOLUTIONS**

The nature of a good research project is to find something new and suitable for the task at hand. For this reason, it is expected that unforeseen problems will present itself during the research and must be overcome. This section list the problems encountered and solutions used to solve them in chronological order.

The single purpose lathe under development is a complex network of computerized control system interfaced with mechanical and pneumatic feed system, hydraulic gripping system, step motor drive system and feedback systems of switches. During the development, many types of problem have occurred and solved. Some of the problems are trivial and should have been foreseen while some only become trivial after careful analysis. These problems are documented for future work and next generation of researchers working on machine tool retrofitting. Each of the problems along with causes and remedies are discussed in turn.

### **Raw Material Hopper Jamming:**

Originally, the hopper for the raw material is designed as a triangular bucket with two sloping walls at forty-five degree. This configuration would work well with material of reasonable surface finish. The raw material used is cast iron caste with sand mold and has very irregular surface finish which cause the material to jam against each other when they converge at the bottom of the hopper and the feed operation become unreliable. The hopper is redesigned as a long rail that hold only one layer of the raw material to solve this problem.

#### Rotary Feeder Impact:

After the hopper is redesigned, the new hopper configuration causes all the raw material mass to sit on the rotary feeder and when the rotary feeder operates, large impact can be felt when a new piece fall in to the rotary feeder slot. The rotary feeder drum is machined to have gradual slope when receiving new part to reduce the impact to acceptable level.

#### Linear Feeder Impact:

During the lathe operation, the raw material is fed through the chuck center hole against the stopper before machining process begins. The original design is to push the material with pneumatic cylinder against the chuck, when the chuck opens, the air pressure will push the material against the stopper. The speed of the material feed will be controlled by the flow control valve attached to the air cylinder. As it happens, the air cylinder is near the end of stroke during the feed cycle and large volume of compressed air is stored behind the piston before the chuck open. When the chuck opens, the compressed air become decompressed and push the material against the stopper at high speed causing large impact. The flow control valve is not in control of the cylinder speed at this moment. The solution is to change the solenoid valve from one solenoid system to two solenoid system to enable the cylinder to unload and release all air pressure during the idle cycle and then push forward only when the chuck begins to open. This change require a new valve, alteration of the system wiring, and alteration of control software.

#### Linear Feeder Air Valve Problem:

The supply pressure to the system is regulated to control the air cylinder force on the raw material. Some of the time, the air valve do not operate properly even though the regulated pressure is well above the valve minimum operating pressure. After extensive testing and installation of a pressure gage behind the regulator, it was found that during the valve opening, the flow is large and cause the regulated pressure supplying the valve to drop below the valve operating pressure and proper opening of the valve cannot be achieved. The regulator has been changed to a large one and regulated pressure increased to rectify the problem.

#### Lathe Bore Adapter Length:

In the original design, the lathe bore adapter will reach just behind the chuck jaw to carry the raw material to the machining area. As it turn out, the chuck jaw is much thicker than expected and some binding can occur during the feeding of the last piece. This can be dangerous because during such time, the chuck is rotating at 1020 rpm. The lathe bore adapter was extended to the front of the chuck grip with slot machined on the end to enable the adapter to carry the part while allowing the chuck to grip the part at the same time.

#### Programmable Peripheral Interface Initialization:

The central processing unit of the control system perform most if it's input and output operation through a 8255 programmable peripheral interface (PPI) integrated circuit. The PPI seems not to function properly after power up but work some of the time after CPU reset. It was found that the PPI require some time after power up and after receiving programming command to work properly. This feature of the PPI chip is not documented anywhere and the source of the problem is found after consultation with an experienced PPI

user. A software delay routine is inserted in to the control program during power up and after PPI programming commands to solve the problem.

#### Stepper Motor Power Supply Overload During Power Up:

All three stepper motors are connected to the CPU via the PPI chip. During power up, a small delay is needed for the PPI to operate properly. During this delay period of about 0.1 second, all of the PPI output is in low state which is the state that turn on stepper motor phases. During this time, the power demand for all the motors far exceed the power supply capability and cause the power transistor of the power supply to be damaged. A relay is added to the system to turn on the stepper motor power supply after the PPI has been initialized to prevent this problem.

#### Assembler Problem:

During testing, the cross slide motor tends to turn on and off randomly. Examination of program code show no apparent explanation for the behavior. CPU boards has been changed with no success. An assistant has been assigned to examine the machine code against the assembly language coding as a last resort of debugging the system. It has been found that the carry flag of the CPU is referred to a symbol 'C' when operation is being done on the flag and during arithmetic operation but when referred to during program branching operation, the machine code produced by the assembler refers to bit number zero in the bit addressable area which control the cross slide motor. This conflict should have been reported as error by the assembler but unintended code was produced instead. When the symbol 'C' has been changed to 'CY' according to Intel convention for program branching operation, the problem was solved. The assembler used is a legally purchased SXA51 8051/8052 cross-assembler version 1.3 by Binary Technology Inc. Meriden, NH, USA.

#### Control Unit Interference:

The control unit was designed as a single enclosure which contain the CPU as well as power resistors and power relays to control the operation of the lathe. Some times the CPU lock up when some of the high power equipment is switched on and off. This problem probably cause by the current surge and the control unit is rewired with separate box containing the power equipment control.

#### Finished Part Taper:

The turning operation is done by the top slide which has a taper adjustment. The finished part shows about 0.02 mm taper when measured with micrometer. It is next to impossible to adjust the top slide normally to compensate for such fine taper so a screw adjustment mechanism is fitted to the slide for fine taper adjustment.

#### Inconsistency of part diameter:

During test runs, it was found that the part diameter vary from one another at random in 0.02 mm increments. Dial indicator is installed on the cross slide to verify the situation and found that the cross slide control lack consistency. Limit switch was tested and found to be repeatable within 0.005 mm and has no connection with the problem. Force of about 50 Kgf was exert on the cross slide tool post and no significant deflection was found. Step rate for the control motor was reduced from 800 steps per second to 400 steps per second and the

problem disappear. The lathe cross slide is programmed so that it slow down before hitting the limit switch.

Part out of round and has unpredictable taper:

Part manufactured by the lathe is out of round and the taper is not predictable. Some part is even smaller around the middle section. The hydraulic pressure to the chuck was increased from 30 bar to 38 bar (the chuck pressure limit is 40 bar) with small improvement. Closer inspection reveal that the chuck grip was worn more in the extremities than the middle. The soft jaw grip was replaced with a set of hard grip provided by SUE and the problem disappear. The hydraulic pressure is set back to 30 bar and the problem did not return.

Flying stub problem:

On some occasions, the ejected stub bounced back from the stopper or the turning tool while it is being ejected and fly toward the rotating chuck. The stub is then thrown out of the chuck with centrifugal force at some respectable velocity. This is deemed to be an operational hazard and a guard plate is installed in front of the chuck to prevent the problem.

Last piece inconsistency:

It was found that the fifth piece machined from each piece of raw material has dimensional variations. The variation take the form of out of round, taper, and diameter error. After numerous trials and monitor of cross slide movement as well as reconditioning of turn slide, the problem persist. During one test, the lathe make strange noise and was switched off immediately and it was found that the linear feeder cannot be retracted. The problem is traced to the tip of linear feeder which interfere with the chuck gripping mechanism. This occur after installation of the guard plate in front of the chuck which necessitate the relocation of the cut off tool. The linear feeder now have to move further to feed the part and interfere with the gripper jaw. The tip of the linear feeder was machined to smaller diameter and solve the problem.

The 'good' part went out of tolerance overnight:

Machined parts changed diameter when left unattended. The staff was asked to verify the collected data on the part diameter and come up with inconsistent results. The same part measured the previous day with the same micrometer just got smaller by 0.01 mm. The person who took the initial measurement was called in to make the measurement again and get the same strange result. The coefficient of expansion for cast iron is 0.000059/F and assuming that the just machined part is at 80 C and the ambient temperature in the morning is 20 C, calculation shows that the part can change its diameter up to 0.0136 mm from this temperature variation. SUE had advised that it is the policy of the plant to reduce the amount of dust and suggest that coolant could be used to solve this problem.

Part diameter change during lathe warm up:

It was observed that the part diameter changes consistently during the first 4 pieces of raw material. The change is about 0.015 mm. The expansion of turning tool may be responsible for this problem. The use of coolant also solved this problem.

The first piece is always larger than the last piece:

The first piece is always larger than the last piece of the raw material by about 0.005 mm. It is speculated that the last piece being machined is hotter than the first one. The use of cutter coolant also solve this problem.

Size measurement is not repeatable:

The same part measured at the same spot twice yield slightly different result. The difference is about 0.003 mm and may be due to smoothing out of surface roughness. The variation is too small to cause any serious problem and is documented for reference.

### **13. PROJECT EVALUATION**

The retrofitted lathe for the first stage of slider production works but it failed occasionally. The mode of failure is almost always traced to electronic parts used in manufacturing of control components. It is a known fact that Thailand is the dump site of barely work electronic parts which has been rejected from various factories around the world. If you wish to see the above mentioned dump site, please tell the Bangkok taxi to drop you off at a place called Clong Thom.

The lathe can produce parts with good consistency and the test data is shown in the appendix. The goal of 30 second cycle time was not achieved due to lack of good stepper motor driver and some oversight during threshing phase and the possible cycle time for this lathe configuration is 40 seconds. This is of no great consequence because by the time that this project was approved, SUE has already plan their new production line and automated machinery ordered. By the time that the project is finished, the new production line is already in use. The old production line can use this lathe as the first stage machining for the slider and the line will be in use soon when SUE increase their production rate again. The lathe will provide the promised prevention of workforce and floor space increase when the production is geared up for 1.5 million units per year.

### **14. CONCLUSION AND SUGGESTIONS**

The microcomputer controlled lathe was built, installed at SUE Udomsuk plant and tested. The development process was challenging and numerous problems have been solved to get the lathe working. Valuable experience has been gained by all parties involve and the know how on production technology of Thailand has went up a notch. For suggestions, if a servo motor drive and PLC controller was used for the lathe, it could have achieve the 30 seconds cycle time targeted with higher reliability. But then, the cost would have tripled.

## References.

1. AB Sandvik Coromant LTD., Turning Tools Catalog. AB Sandvik Coromant LTD., Sandviken, Sweden, 1995, p 12.
2. E. Paul DeGarmo, Material and Processes in Manufacturing, Fifth Edition, Macmillan Publishing Co., INC. New York, 1979, p 517.
3. E. Paul DeGarmo, Material and Processes in Manufacturing, Fifth Edition, Macmillan Publishing Co., INC. New York, 1979, p 532.
4. Sanyo Denki Co., LTD, Stepping Motor Step-Syn Catalog No. 560- 1 88.8.2DB, Sanyo Denki Co., LTD., Japan, 1988, p 43.

## Appendix A. Timer Reload Value Table

Hz Reload Hz Reload Hz Reload Hz Reload Hz Reload Hz Reload

|    |       |     |       |     |       |     |       |     |       |     |       |
|----|-------|-----|-------|-----|-------|-----|-------|-----|-------|-----|-------|
| 15 | 4090  | 65  | 51352 | 115 | 57516 | 165 | 59945 | 215 | 61243 | 265 | 62052 |
| 16 | 7930  | 66  | 51566 | 116 | 57585 | 166 | 59978 | 216 | 61263 | 266 | 62065 |
| 17 | 11318 | 67  | 51775 | 117 | 57653 | 167 | 60011 | 217 | 61283 | 267 | 62078 |
| 18 | 14330 | 68  | 51977 | 118 | 57720 | 168 | 60044 | 218 | 61302 | 268 | 62091 |
| 19 | 17025 | 69  | 52173 | 119 | 57785 | 169 | 60077 | 219 | 61322 | 269 | 62104 |
| 20 | 19450 | 70  | 52364 | 120 | 57850 | 170 | 60109 | 220 | 61341 | 270 | 62117 |
| 21 | 21644 | 71  | 52550 | 121 | 57913 | 171 | 60141 | 221 | 61360 | 271 | 62129 |
| 22 | 23639 | 72  | 52730 | 122 | 57976 | 172 | 60172 | 222 | 61379 | 272 | 62142 |
| 23 | 25460 | 73  | 52905 | 123 | 58037 | 173 | 60203 | 223 | 61397 | 273 | 62154 |
| 24 | 27130 | 74  | 53076 | 124 | 58098 | 174 | 60233 | 224 | 61416 | 274 | 62166 |
| 25 | 28666 | 75  | 53242 | 125 | 58157 | 175 | 60264 | 225 | 61434 | 275 | 62179 |
| 26 | 30084 | 76  | 53404 | 126 | 58216 | 176 | 60294 | 226 | 61452 | 276 | 62191 |
| 27 | 31397 | 77  | 53561 | 127 | 58273 | 177 | 60323 | 227 | 61470 | 277 | 62203 |
| 28 | 32616 | 78  | 53715 | 128 | 58330 | 178 | 60352 | 228 | 61488 | 278 | 62215 |
| 29 | 33751 | 79  | 53864 | 129 | 58386 | 179 | 60381 | 229 | 61506 | 279 | 62227 |
| 30 | 34810 | 80  | 54010 | 130 | 58441 | 180 | 60410 | 230 | 61523 | 280 | 62239 |
| 31 | 35801 | 81  | 54152 | 131 | 58495 | 181 | 60438 | 231 | 61540 | 281 | 62250 |
| 32 | 36730 | 82  | 54291 | 132 | 58548 | 182 | 60466 | 232 | 61558 | 282 | 62262 |
| 33 | 37603 | 83  | 54426 | 133 | 58601 | 183 | 60494 | 233 | 61575 | 283 | 62273 |
| 34 | 38424 | 84  | 54559 | 134 | 58652 | 184 | 60521 | 234 | 61592 | 284 | 62285 |
| 35 | 39199 | 85  | 54688 | 135 | 58703 | 185 | 60548 | 235 | 61608 | 285 | 62296 |
| 36 | 39930 | 86  | 54814 | 136 | 58754 | 186 | 60575 | 236 | 61625 | 286 | 62308 |
| 37 | 40622 | 87  | 54937 | 137 | 58803 | 187 | 60602 | 237 | 61641 | 287 | 62319 |
| 38 | 41277 | 88  | 55057 | 138 | 58852 | 188 | 60628 | 238 | 61658 | 288 | 62330 |
| 39 | 41899 | 89  | 55175 | 139 | 58900 | 189 | 60654 | 239 | 61674 | 289 | 62341 |
| 40 | 42490 | 90  | 55290 | 140 | 58947 | 190 | 60679 | 240 | 61690 | 290 | 62352 |
| 41 | 43052 | 91  | 55403 | 141 | 58994 | 191 | 60705 | 241 | 61706 | 291 | 62363 |
| 42 | 43587 | 92  | 55513 | 142 | 59040 | 192 | 60730 | 242 | 61722 | 292 | 62374 |
| 43 | 44097 | 93  | 55620 | 143 | 59085 | 193 | 60755 | 243 | 61737 | 293 | 62385 |
| 44 | 44585 | 94  | 55726 | 144 | 59130 | 194 | 60779 | 244 | 61753 | 294 | 62395 |
| 45 | 45050 | 95  | 55829 | 145 | 59174 | 195 | 60804 | 245 | 61768 | 295 | 62406 |
| 46 | 45495 | 96  | 55930 | 146 | 59218 | 196 | 60828 | 246 | 61784 | 296 | 62416 |
| 47 | 45921 | 97  | 56029 | 147 | 59261 | 197 | 60852 | 247 | 61799 | 297 | 62427 |
| 48 | 46330 | 98  | 56126 | 148 | 59303 | 198 | 60875 | 248 | 61814 | 298 | 62437 |
| 49 | 46722 | 99  | 56221 | 149 | 59345 | 199 | 60899 | 249 | 61829 | 299 | 62448 |
| 50 | 47098 | 100 | 56314 | 150 | 59386 | 200 | 60922 | 250 | 61844 | 300 | 62458 |
| 51 | 47459 | 101 | 56405 | 151 | 59427 | 201 | 60945 | 251 | 61858 | 301 | 62468 |
| 52 | 47807 | 102 | 56495 | 152 | 59467 | 202 | 60968 | 252 | 61873 | 302 | 62478 |
| 53 | 48141 | 103 | 56582 | 153 | 59506 | 203 | 60990 | 253 | 61887 | 303 | 62488 |
| 54 | 48463 | 104 | 56668 | 154 | 59546 | 204 | 61012 | 254 | 61902 | 304 | 62498 |
| 55 | 48774 | 105 | 56753 | 155 | 59584 | 205 | 61034 | 255 | 61916 | 305 | 62508 |
| 56 | 49073 | 106 | 56836 | 156 | 59622 | 206 | 61056 | 256 | 61930 | 306 | 62518 |
| 57 | 49362 | 107 | 56917 | 157 | 59660 | 207 | 61078 | 257 | 61944 | 307 | 62528 |
| 58 | 49640 | 108 | 56997 | 158 | 59697 | 208 | 61099 | 258 | 61958 | 308 | 62538 |
| 59 | 49910 | 109 | 57075 | 159 | 59734 | 209 | 61120 | 259 | 61972 | 309 | 62547 |
| 60 | 50170 | 110 | 57152 | 160 | 59770 | 210 | 61141 | 260 | 61985 | 310 | 62557 |
| 61 | 50422 | 111 | 57227 | 161 | 59806 | 211 | 61162 | 261 | 61999 | 311 | 62567 |
| 62 | 50665 | 112 | 57301 | 162 | 59841 | 212 | 61183 | 262 | 62012 | 312 | 62576 |
| 63 | 50901 | 113 | 57374 | 163 | 59876 | 213 | 61203 | 263 | 62026 | 313 | 62586 |
| 64 | 51130 | 114 | 57446 | 164 | 59910 | 214 | 61223 | 264 | 62039 | 314 | 62595 |

Appendix A. Timer Reload Value Table (continue)

| Hz Reload | Hz Reload | Hz Reload | Hz Reload | Hz Reload | Hz Reload |
|-----------|-----------|-----------|-----------|-----------|-----------|
| 315       | 62604 365 | 63005 415 | 63309 465 | 63548 515 | 63740 565 |
| 316       | 62614 366 | 63012 416 | 63315 466 | 63552 516 | 63744 566 |
| 317       | 62623 367 | 63019 417 | 63320 467 | 63557 517 | 63747 567 |
| 318       | 62632 368 | 63026 418 | 63325 468 | 63561 518 | 63751 568 |
| 319       | 62641 369 | 63032 419 | 63330 469 | 63565 519 | 63754 569 |
| 320       | 62650 370 | 63039 420 | 63336 470 | 63569 520 | 63758 570 |
| 321       | 62659 371 | 63046 421 | 63341 471 | 63573 521 | 63761 571 |
| 322       | 62668 372 | 63053 422 | 63346 472 | 63577 522 | 63764 572 |
| 323       | 62677 373 | 63059 423 | 63351 473 | 63582 523 | 63768 573 |
| 324       | 62686 374 | 63066 424 | 63356 474 | 63586 524 | 63771 574 |
| 325       | 62694 375 | 63072 425 | 63362 475 | 63590 525 | 63775 575 |
| 326       | 62703 376 | 63079 426 | 63367 476 | 63594 526 | 63778 576 |
| 327       | 62712 377 | 63085 427 | 63372 477 | 63598 527 | 63781 577 |
| 328       | 62720 378 | 63092 428 | 63377 478 | 63602 528 | 63785 578 |
| 329       | 62729 379 | 63098 429 | 63382 479 | 63606 529 | 63788 579 |
| 330       | 62737 380 | 63105 430 | 63387 480 | 63610 530 | 63791 580 |
| 331       | 62746 381 | 63111 431 | 63392 481 | 63614 531 | 63794 581 |
| 332       | 62754 382 | 63117 432 | 63397 482 | 63618 532 | 63798 582 |
| 333       | 62762 383 | 63124 433 | 63402 483 | 63622 533 | 63801 583 |
| 334       | 62771 384 | 63130 434 | 63406 484 | 63626 534 | 63804 584 |
| 335       | 62779 385 | 63136 435 | 63411 485 | 63630 535 | 63807 585 |
| 336       | 62787 386 | 63142 436 | 63416 486 | 63634 536 | 63811 586 |
| 337       | 62795 387 | 63149 437 | 63421 487 | 63638 537 | 63814 587 |
| 338       | 62803 388 | 63155 438 | 63426 488 | 63641 538 | 63817 588 |
| 339       | 62811 389 | 63161 439 | 63431 489 | 63645 539 | 63820 589 |
| 340       | 62819 390 | 63167 440 | 63435 490 | 63649 540 | 63823 590 |
| 341       | 62827 391 | 63173 441 | 63440 491 | 63653 541 | 63826 591 |
| 342       | 62835 392 | 63179 442 | 63445 492 | 63657 542 | 63830 592 |
| 343       | 62843 393 | 63185 443 | 63450 493 | 63661 543 | 63833 593 |
| 344       | 62851 394 | 63191 444 | 63454 494 | 63664 544 | 63836 594 |
| 345       | 62859 395 | 63197 445 | 63459 495 | 63668 545 | 63839 595 |
| 346       | 62866 396 | 63203 446 | 63464 496 | 63672 546 | 63842 596 |
| 347       | 62874 397 | 63209 447 | 63468 497 | 63676 547 | 63845 597 |
| 348       | 62882 398 | 63214 448 | 63473 498 | 63679 548 | 63848 598 |
| 349       | 62889 399 | 63220 449 | 63477 499 | 63683 549 | 63851 599 |
| 350       | 62897 400 | 63226 450 | 63482 500 | 63687 550 | 63854 600 |
| 351       | 62904 401 | 63232 451 | 63487 501 | 63690 551 | 63857 601 |
| 352       | 62912 402 | 63237 452 | 63491 502 | 63694 552 | 63860 602 |
| 353       | 62919 403 | 63243 453 | 63496 503 | 63698 553 | 63863 603 |
| 354       | 62927 404 | 63249 454 | 63500 504 | 63701 554 | 63866 604 |
| 355       | 62934 405 | 63254 455 | 63505 505 | 63705 555 | 63869 605 |
| 356       | 62941 406 | 63260 456 | 63509 506 | 63709 556 | 63872 606 |
| 357       | 62948 407 | 63266 457 | 63513 507 | 63712 557 | 63875 607 |
| 358       | 62956 408 | 63271 458 | 63518 508 | 63716 558 | 63878 608 |
| 359       | 62963 409 | 63277 459 | 63522 509 | 63719 559 | 63881 609 |
| 360       | 62970 410 | 63282 460 | 63527 510 | 63723 560 | 63884 610 |
| 361       | 62977 411 | 63288 461 | 63531 511 | 63726 561 | 63887 611 |
| 362       | 62984 412 | 63293 462 | 63535 512 | 63730 562 | 63890 612 |
| 363       | 62991 413 | 63299 463 | 63540 513 | 63734 563 | 63893 613 |
| 364       | 62998 414 | 63304 464 | 63544 514 | 63737 564 | 63896 614 |

Appendix A. Timer Reload Value Table (continue)

| Hz Reload | Hz Reload | Hz Reload | Hz Reload | Hz Reload | Hz Reload |
|-----------|-----------|-----------|-----------|-----------|-----------|
| 615       | 64031 665 | 64144 715 | 64241 765 | 64325 815 | 64399 865 |
| 616       | 64034 666 | 64146 716 | 64243 766 | 64327 816 | 64401 866 |
| 617       | 64036 667 | 64148 717 | 64245 767 | 64328 817 | 64402 867 |
| 618       | 64039 668 | 64150 718 | 64246 768 | 64330 818 | 64403 868 |
| 619       | 64041 669 | 64152 719 | 64248 769 | 64332 819 | 64405 869 |
| 620       | 64044 670 | 64154 720 | 64250 770 | 64333 820 | 64406 870 |
| 621       | 64046 671 | 64157 721 | 64252 771 | 64335 821 | 64407 871 |
| 622       | 64048 672 | 64159 722 | 64254 772 | 64336 822 | 64409 872 |
| 623       | 64051 673 | 64161 723 | 64255 773 | 64338 823 | 64410 873 |
| 624       | 64053 674 | 64163 724 | 64257 774 | 64339 824 | 64412 874 |
| 625       | 64055 675 | 64165 725 | 64259 775 | 64341 825 | 64413 875 |
| 626       | 64058 676 | 64167 726 | 64261 776 | 64342 826 | 64414 876 |
| 627       | 64060 677 | 64169 727 | 64262 777 | 64344 827 | 64416 877 |
| 628       | 64062 678 | 64171 728 | 64264 778 | 64345 828 | 64417 878 |
| 629       | 64065 679 | 64173 729 | 64266 779 | 64347 829 | 64418 879 |
| 630       | 64067 680 | 64175 730 | 64268 780 | 64348 830 | 64420 880 |
| 631       | 64069 681 | 64177 731 | 64269 781 | 64350 831 | 64421 881 |
| 632       | 64072 682 | 64179 732 | 64271 782 | 64351 832 | 64422 882 |
| 633       | 64074 683 | 64181 733 | 64273 783 | 64353 833 | 64424 883 |
| 634       | 64076 684 | 64183 734 | 64274 784 | 64354 834 | 64425 884 |
| 635       | 64079 685 | 64185 735 | 64276 785 | 64356 835 | 64426 885 |
| 636       | 64081 686 | 64187 736 | 64278 786 | 64357 836 | 64428 886 |
| 637       | 64083 687 | 64189 737 | 64280 787 | 64359 837 | 64429 887 |
| 638       | 64085 688 | 64190 738 | 64281 788 | 64360 838 | 64430 888 |
| 639       | 64088 689 | 64192 739 | 64283 789 | 64362 839 | 64432 889 |
| 640       | 64090 690 | 64194 740 | 64285 790 | 64363 840 | 64433 890 |
| 641       | 64092 691 | 64196 741 | 64286 791 | 64365 841 | 64434 891 |
| 642       | 64094 692 | 64198 742 | 64288 792 | 64366 842 | 64435 892 |
| 643       | 64097 693 | 64200 743 | 64290 793 | 64368 843 | 64437 893 |
| 644       | 64099 694 | 64202 744 | 64291 794 | 64369 844 | 64438 894 |
| 645       | 64101 695 | 64204 745 | 64293 795 | 64371 845 | 64439 895 |
| 646       | 64103 696 | 64206 746 | 64295 796 | 64372 846 | 64441 896 |
| 647       | 64106 697 | 64208 747 | 64296 797 | 64374 847 | 64442 897 |
| 648       | 64108 698 | 64210 748 | 64298 798 | 64375 848 | 64443 898 |
| 649       | 64110 699 | 64212 749 | 64300 799 | 64377 849 | 64444 899 |
| 650       | 64112 700 | 64213 750 | 64301 800 | 64378 850 | 64446 900 |
| 651       | 64114 701 | 64215 751 | 64303 801 | 64379 851 | 64447 901 |
| 652       | 64117 702 | 64217 752 | 64304 802 | 64381 852 | 64448 902 |
| 653       | 64119 703 | 64219 753 | 64306 803 | 64382 853 | 64450 903 |
| 654       | 64121 704 | 64221 754 | 64308 804 | 64384 854 | 64451 904 |
| 655       | 64123 705 | 64223 755 | 64309 805 | 64385 855 | 64452 905 |
| 656       | 64125 706 | 64225 756 | 64311 806 | 64387 856 | 64453 906 |
| 657       | 64127 707 | 64226 757 | 64313 807 | 64388 857 | 64455 907 |
| 658       | 64129 708 | 64228 758 | 64314 808 | 64389 858 | 64456 908 |
| 659       | 64132 709 | 64230 759 | 64316 809 | 64391 859 | 64457 909 |
| 660       | 64134 710 | 64232 760 | 64317 810 | 64392 860 | 64458 910 |
| 661       | 64136 711 | 64234 761 | 64319 811 | 64394 861 | 64460 911 |
| 662       | 64138 712 | 64236 762 | 64321 812 | 64395 862 | 64461 912 |
| 663       | 64140 713 | 64237 763 | 64322 813 | 64396 863 | 64462 913 |
| 664       | 64142 714 | 64239 764 | 64324 814 | 64398 864 | 64463 914 |

## Appendix B. Firmware Program Listing.

Program MTEST.ASM last update 28 Jan 1997

### PROGRAM DESCRIPTION

This program is written to control a single purpose lathe which is a joint research effort between CMU, TDO, and SUE. The hardware used for this program is Sila Research ANT-32 micro controller board equipped with Intel 8032 microprocessor. The main control function is done in the foreground while stepper motor operation is carried out with 2 levels of timer interrupt. The assembler used is SXA51 8051/8052 cross-assembler version 1.3 by Binary Technology Inc. Meriden, NH, USA.

In case of difficulties, the programmer can be reached at:

Thawan Sucharitakul  
Department of Mechanical Engineering  
Faculty of Engineering  
Chiang Mai University, Chiang Mai 50200  
THAILAND  
Phone and Fax: (053) 210-320  
E-Mail enagi001@chiangmai.ac.th

### HARDWARE CONFIGURATION

8255 PPI #1 at data memory F800h - F803h operate in mode 0  
8255 PPI #2 at data memory FC00h - FC03h operate in mode 0

| PORT | I/O | ACTIVE | DESCRIPTION                  |
|------|-----|--------|------------------------------|
| U1A0 | O   | LOW    | MOTOR0 (CUT) PHASE A         |
| U1A1 | O   | LOW    | MOTOR0 (CUT) PHASE B         |
| U1A2 | O   | LOW    | MOTOR0 (CUT) PHASE C         |
| U1A3 | O   | LOW    | MOTOR0 (CUT) PHASE D         |
| U1A4 | O   | LOW    | MOTOR1 (TURN) PHASE A        |
| U1A5 | O   | LOW    | MOTOR1 (TURN) PHASE B        |
| U1A6 | O   | LOW    | MOTOR1 (TURN) PHASE C        |
| U1A7 | O   | LOW    | MOTOR1 (TURN) PHASE D        |
| U1B0 | O   | HIGH   | STEPPER MOTOR POWER          |
| U1B1 | O   | HIGH   | ROTARY FEEDER MOTOR          |
| U1B2 | O   | HIGH   | LINEAR FEEDER BACK           |
| U1B3 | O   | HIGH   | LINEAR FEEDER FORWARD        |
| U1B4 | O   | HIGH   | CHUCK CONTROL                |
| U1B5 | O   | HIGH   | HYDRAULIC PUMP POWER         |
| U1B6 | O   | HIGH   | LATHE POWER CONTROL          |
| U1B7 | O   | HIGH   | READY LAMP                   |
| U1C0 | I   | HIGH   | HOPPER EMPTY SWITCH          |
| U1C1 | I   | LOW    | LINEAR FEEDER FULL IN SWITCH |
| U1C2 | I   | LOW    | LINEAR FEEDER STUB SWITCH    |
| U1C3 | I   | LOW    | TURNING SLIDE HOME SWITCH    |
| U1C4 | I   | LOW    | CUT OFF SLIDE HOME SWITCH    |
| U1C5 | I   | LOW    | STOPPER HOME SWITCH          |
| U1C6 | I   | LOW    | SPARE                        |

01 CROSS LIMIT  
Cross slide did not leave limit switch in forward motion.  
Possible causes: loose coupling, low or missing stepper supply,  
loose limit switch, limit switch malfunction,  
limit switch wiring short circuit, step motor  
wiring bad, step motor driver bad, resistor pack  
open circuit, slider jammed, chuck not turning.

02 CROSS STROKE  
Cross slide forward stroke too short.  
Possible causes: loose coupling, low stepper supply,  
slider jammed, chuck not turning.

03 CROSS NOT RET  
Cross slide cannot reach home position.  
Possible causes: loose coupling, low stepper supply,  
slider jammed, loose limit switch, limit  
switch malfunction, limit switch wiring  
open circuit, step rate set too high.

Appendix B. Firmware Program Listing (continue).

```
: 04 TURN LIMIT
:   Turn slide did not leave limit switch in forward motion.
:   Possible causes: loose coupling, low or missing stepper supply,
:                   loose limit switch, limit switch malfunction,
:                   limit switch wiring short circuit, step motor
:                   wiring bad, step motor driver bad, resistor pack
:                   open circuit, slider jammed, chuck not turning.
: 05 TURN STROKE
:   Turn slide forward stroke too short.
:   Possible causes: loose coupling, low stepper supply,
:                   slider jammed, chuck not turning.
: 06 TURN NOT RET
:   Turn slide cannot reach home position.
:   Possible causes: loose coupling, low stepper supply,
:                   slider jammed, loose limit switch, limit
:                   switch malfunction, limit switch wiring
:                   open circuit, step rate set too high.
: 07 STOPPER LIMIT
:   Stopper did not leave limit switch in forward motion.
:   Possible causes: loose coupling, low or missing stepper supply,
:                   loose limit switch, limit switch malfunction,
:                   limit switch wiring short circuit, step motor
:                   wiring bad, step motor driver bad, resistor pack
:                   open circuit, slider jammed, chuck did not open,
:                   stopper gear box not in proper position.
: 08 STOP STROKE
:   Stopper forward stroke too short.
:   Possible causes: loose coupling, low stepper supply,
:                   slider jammed, chuck did not open.
: 09 STOP NOT RET
:   Stopper cannot reach home position.
:   Possible causes: loose coupling, low stepper supply,
:                   loose limit switch, limit switch malfunction,
:                   limit switch wiring open circuit, step rate
:                   set too high, stopper gear box not in proper
:                   position.
: 10 CHUCK NOT CLR
:   Raw material remain in the chuck during self test.
:   Possible causes: Raw material remain in the chuck during self test,
:                   low or missing air supply, bad air solenoid valve,
:                   low or missing 24 volt supply, forward reed switch
:                   not in proper place or loose, reed switch malfunction,
:                   chuck did not open, linear slider jammed.
: 11 LINEAR NOT RE
:   Linear feeder cannot move back to full in position.
:   Possible causes: Low or missing air supply, bad air solenoid valve,
:                   low or missing 24 volt supply, back reed switch
:                   not in proper place or loose, reed switch malfunction,
:                   chuck did not open, linear slider jammed.
: 12 ROTARY PROB.
:   Rotary feeder problem, no part is fed when commanded.
:   Possible causes: Low or missing 12V supply, feeder jammed, short
:                   circuit in hopper switch or wiring, broken rotary
:                   feeder limit switch, bad rotary feeder wiring.
: 13 HOPPER EMPTY
:   There is no raw material in the hopper.
:   Possible causes: There is no raw material in the hopper, bad hopper
:                   switch, open circuit in hopper switch wiring.
```

```
:      material jammed in the upper part of the hopper.  
:      limit switch arm bent  
: 14 EMERGENCY ST  
:      Emergency stop switch pressed, system shut down immediately.  
:      Possible causes: Emergency stop switch pressed, emergency stop  
:      switch malfunction, front panel circuit board  
:      malfunction.  
: 15 STOPPED  
:      Stop switch pressed, system stop at end of machining cycle.  
:      resume by pressing GO or press stop again for system  
:      shut down.  
:      Possible causes: Stop switch pressed, stop switch malfunction,  
:      front panel circuit board malfunction.  
: 16 COUNT ERROR  
:      Stub sensor did not read stub after 5 cylinders was machined.  
:
```

:DEFINE PORT ADDRESSE

```
  aprot1 equ 0F800h   :Port A of 8255-1  
  bprot1 equ aprot1+1 :Port B of 8255-1  
  cprot1 equ bprot1+1 :Port C of 8255-1  
  rprot1 equ cprot1+1 :Control register of 8255-1  
  aprot2 equ 0FC00h   :Port A of 8255-2  
  bprot2 equ aprot2+1 :Port B of 8255-2  
  cprot2 equ bprot2+1 :Port C of 8255-2  
  rprot2 equ cprot2+1 :Control register of 8255-2  
  wr_inst equ 0FA00h  :Write instruction port of LCD  
  rd_busy equ 0FA01h  :Read busy instruction port of LCD  
  wr_data equ 0FA02h  :Write data port of LCD  
  rd_data equ 0FA03h  :Read data port of LCD
```

:DEFINE VARIABLES IN BIT ADDRESSABLE AREA (128 bit max)

```
  m0done bit 00h      :Motor 0 done  
  m0rev  bit m0done+1 :Motor 0 reverse  
  m0tsel bit m0rev+1  :Motor 0 timer select  
  m1done bit m0tsel+1 :Motor 1 done  
  m1rev  bit m1done+1 :Motor 1 reverse  
  m1tsel bit m1rev+1  :Motor 1 timer select  
  m2done bit m1tsel+1 :Motor 2 done  
  m2rev  bit m2done+1 :Motor 2 reverse  
  m2tsel bit m2rev+1  :Motor 2 timer select  
  stopped bit m2tsel+1 :Stop request flag  
  estop  bit stopped+1 :Emergency stop request flag  
  stub   bit estop+1   :Stub detection flsg  
  m0speed bit stub+1   :Cross slide speed up  
  holdm0 bit m0speed+1 :Cross slide hold  
  mes1   bit holdm0+1  :enable massage set 1  
  m0dbo  bit mes1+1    :Motor 0 limit switch debounce
```

:DEFINE VARIABLES IN MEMORY (36 byte max, change SP if need more)

```
  m0sth equ 30h       :Motor 0 step count high byte  
  m0stl equ m0sth+1   :Motor 0 step count low byte  
  m0ph  equ m0stl+1   :Phase count motor 0  
  m1sth equ m0ph+1    :Motor 1 step count high byte  
  m1stl equ m1sth+1   :Motor 1 step count low byte  
  m1ph  equ m1stl+1   :Phase count motor 1  
  m2sth equ m1ph+1    :Motor 2 step count high byte  
  m2stl equ m2sth+1   :Motor 2 step count low byte  
  m2ph  equ m2stl+1   :Phase count motor 2  
  relo0h equ m2ph+1   :Timer0 reload high byte  
  relo0l equ relo0h+1 :Timer0 reload low byte
```

```

relo1h equ relo0+1    ;Timer1 reload high byte
relo1l equ relo1h+1    ;Timer1 reload low byte
error equ relo1l+1     ;Error code
phomeh equ error+1     ;post home pos. high byte M0 only
phomel equ phomeh+1    ;post home pos. low byte
pcount equ phomel-1    ;Piece count during machining
m0hold equ pcount-1    ;Motor 0 hold period

;reload value = 0FFFFh - crystal frequency / (12*step rate) - 5
;FFFF = 65535, crystal frequency = 11,059,200 Hz
m0fstroke equ 1700    ;15mm / 4mm/rev * 400steps/rev = 1500steps
m0rstroke equ 1800    ;16mm / 4mm/rev * 400steps/rev = 1600steps
m0begment equ 1400    ;begin cut at 11 mm from center
m0fstroke equ 600     ;3.35mm/4mm/rev*400steps/rev = 335 steps
m0cutrelo equ 60109   ;cut speed reload value 170 Hz
m0movrelo equ 63039   ;move speed reload value 370 Hz
m0limrelo equ 57850   ;Hit limit switch speed 120 Hz
m1fstroke equ 2100    ;30mm / 3mm/rev * 200steps/rev = 2000steps
m1fstroke1 equ 1800   ;Ready for clean up for facing
m1fstroke2 equ 300    ;Clean up for facing
m1rstroke equ 2150    ;33mm / 3mm/rev * 200steps/rev = 2200steps
; m1cutrelo equ 60109 ;cut speed reload value 170 Hz
m1cutrelo equ 58703   ;cut speed reload value 135 Hz
m1movrelo equ 61844   ;move speed reload value 250 Hz
m2fstroke1 equ 494    ;10mm / 4mm/rev * 200steps/rev = 500 steps
m2rstroke1 equ 580    ;12mm / 4mm/rev * 200steps/rev = 600 steps
m2fstroke2 equ 1850   ;37mm / 4mm/rev * 200steps/rev = 1850steps
m2rstroke2 equ 1950   ;39mm / 4mm/rev * 200steps/rev = 1950steps
m2fstroke3 equ 2000   ;40mm / 4mm/rev * 200steps/rev = 2000steps
m2rstroke3 equ 2100   ;42mm / 4mm/rev * 200steps/rev = 2100steps
m2movrelo equ 62117   ;move speed reload value 270 Hz

org 00h          ;PC location after reset
jmp MAIN         ;go to main program

org 0Bh          ;PC location for timer0 interrupt
jmp STEP0        ;go to timer0 interrupt service routine

org 1Bh          ;PC location for timer1 interrupt
Appendix B. Firmware Program Listing (continue).

jmp STEP1        ;go to timer1 interrupt service routine

org 100h         ;start location of main program
MAIN:            ;Main program start here
mov SP,#4Fh      ;set stack pointer for 64 byte stack area
call INI8255     ;Get 8255 port ready
call INIVARS     ;Initiate variables
call INICLOCK    ;Initiate timer interrupt
call INIT_LCD    ;Set up LCD display
call CHUCK_OPEN  ;Open chuck head
call STEP_POWER_ON ;Turn on 12V supply
call WAITONE     ;Wait one second
call READY_LAMP_ON ;Turn on ready lamp
MAINLOOP:
call READ_TEST   ;Read test switch

```

```
jnz  MAINLOOP1    :Loop if no test
call  RUN1
jmp   MAINLOOP
MAINLOOP1:
call  TEST0        :Go to test routine
jmp   MAINLOOP     :Loop again
```

INISYS: :Initialize system and test components

```
setb  mes1
mov   a.#1
call  DISPLAY
call  ALARM_LAMP_OFF :Turn off alarm lamp
call  HYD_POWER_ON   :Power up hydraulic pump
call  CHUCK_OPEN     :Open chuck grip
call  WAITONE        :Wait two seconds for hydraulic pressure
call  WAITONE
call  LINEAR_F_BACK   :Move linear feeder full back
call  LINEAR_OFF      :Unload linear feeder
call  CHECK_LINEAR_B  :Check linear feeder back switch
call  M0HOME          :Home cross slide
call  WAITM0          :Wait until done
call  CHECK_CROSS_H   :See if cross slide home properly
call  M1HOME          :Home turn slide
call  WAITM1          :Wait until done
call  CHECK_TURN_H    :See if turn slide home properly
call  M2HOMEPOS3      :Home stopper
call  WAITM2          :Wait until done
call  WAIT            :switch bounce?
call  CHECK_STOP_H    :See if stopper home properly
call  WAIT            :Wait 0.1 sec
call  M2POS3          :Push stopper all the way in
call  WAITM2          :Wait until done
call  CHECK_STOP_F    :Check stopper forward operation
call  WAIT            :Wait 1/10 sec
call  M2HOMEPOS3      :Home stopper
call  WAITM2          :Wait until done
call  CHECK_STOP_R    :Check stopper operation
call  M0CUT           :Move cross slide
call  WAITM0          :Wait for cross slide done
call  CHECK_CROSS_F   :Check cross slide forward motion
call  WAIT            :Wait 1/10 sec before motor reversal
call  M0HOME          :Move cross slide home
call  WAITM0          :Wait for cross slide to home
call  CHECK_CROSS_R   :Check cross slide operation
call  M1TURN          :Move turn slide
call  WAITM1          :Wait for turn slide to finish
call  CHECK_TURN_F    :Check turn slide forward motion
call  WAIT            :Wait 1/10 sec before motor reversal
call  M1HOME          :Home turn slide
call  WAITM1          :Wait for turn slide to home
call  CHECK_TURN_R    :Check turn slide reverse motion
call  M2POS1          :Move stopper in
call  M0_OFF_LIMIT    :Move cross slide off limit sw.
call  WAITM0          :Wait till done
call  WAIT            :Wait 1/10 sec.
call  M0TURN          :Move turning tool to turn position
call  WAITM0          :Wait for cross slide
call  CHECK_CROSS_H   :See if cross slide home properly
call  WAITM2          :Wait for stopper
```

```
call CHECK_STOP_F :Check stopper forward operation
call LINEAR_F_FWD :Move linear feeder in
call LINEAR_OFF :Unload linear feeder
mov a.error :Check error
jnz INISYS_ERR :Chuck not clear, stop system
call WAITONE :Wait for linear feeder to unload
call LINEAR_F_BACK :Move linear feeder back
mov a.error :Check for problem
jnz INISYS_ERR :No air pressure, stop system
setb mes1
mov a.#15
call DISPLAY
ret
INISYS_ERR: :The jnz command cannot make long jump
jmp ALL_STOP :Stop all system and flash alarm
```

```
PART_FEED: :Feed new part and facing
setb mes1
mov a.#2
call DISPLAY
call READ_HOPPER :Check hopper switch
jz PART_FEED_A :Skip if not empty
mov error.#13
jmp HOPPER_EMPTY :Go to hopper empty condition
```

```
PART_FEED_A:
call CHUCK_OPEN :Make sure chuck is open
call M2HOMEPOS1 :Home stopper
call WAITM2 :Wait for stopper
call CHECK_STOP_H :See if stopper home properly
call WAIT :Wait 1/10 sec before motor reversal
call M2POS2 :Begin move stopper in
call M1TURN1 :Move turning tool to ready position
call LINEAR_F_BACK :Move linear feeder back
mov a.error :Check for problem
jnz INISYS_ERR :No air pressure, stop system
call ROTARY_GO :Activate rotary feeder
call WAITONE :Wait one second
call WAITM2 :Wait for stopper to finish moving
call CHECK_STOP_F :Stopper left limit switch?
call WAITM1 :Wait for turning tool to finish
call CHECK_TURN_F :Turn slide left limit switch?
call LINEAR_F_FWD :Linear feeder in
mov a.error
jnz PART_FEED_B :PROBLEM!! part not in, rotary feeder problem
mov error.#12
jmp ALL_STOP
```

```
PART_FEED_B:
call CHUCK_CLOSE :Close chuck
call WAITONE :Wait for chuck to close
call LINEAR_OFF :Unload linear feeder
call M2HOMEPOS2 :Home stopper
call M1TURN2 :Turn to get ready for facing
call WAITM1 :Wait for turning done
call M0CUT :Cut off the face
call WAIT :Wait 1/10 sec before motor reversal
call M1HOME :Home turn slide
call WAITM0 :Wait for cross slide
call CHECK_CROSS_F :Cross slide left limit switch?
call WAIT :Delay 1/10 sec
```

```
call M0TURN      :Position cross slide for turning
call WAITM1      :Wait for turn slide to finish
call CHECK_TURN_R :Check turn slide reversal motion
call WAITM2      :Wait for stopper to finish
call CHECK_STOP_R :Check stopper reversal motion
call WAIT        :Wait before stopper reversal
call M2POS1      :Move stopper in to place
call WAITM0      :Wait for cross slide
call CHECK_CROSS_H :Check cross slide home?
call WAITM2      :Wait for stopper
call CHECK_STOP_F :Stopper left limit switch?
setb mes1
mov a,#15
call DISPLAY
ret
```

```
MAKE_SLIDE:      :Make slider part
setb mes1
mov a,#3
call DISPLAY
call FEED_AND_CHECK :Feed material and check for stub
call M2HOMEPOS1    :Home stopper
call M1TURN        :Turn the part
call WAITM1        :Wait for turning to finish
call CHECK_TURN_F  :Turning slide off limit sw?
call CHECK_STOP_H  :Stopper home OK?
call M0CUT         :Begin cutting off
call WAIT          :Wait 1/10 sec before motor reversal
call M1HOME        :Home turning slide
call WAITM0        :Wait for cutting done
call CHECK_CROSS_F :Cross slide left limit sw?
call WAIT          :Wait 1/10 sec before motor reversal
call M0TURN        :Return cross slide
call WAITM1        :Wait for turn slide to home
call CHECK_TURN_R  :Turn slide movement OK?
call M2POS1        :Move stopper in
call WAITM0        :Wait for cross slide
call CHECK_CROSS_H :Cross slide movement OK?
call WAITM2        :Wait for stopper
call CHECK_STOP_F  :Stopper left sw OK?
setb mes1
mov a,#15
call DISPLAY
ret
```

```
EJECT_STUB:      :Eject remaining stub
setb mes1
mov a,#4
call DISPLAY
call M0_OFF_LIMIT  :Move cross slide off limit switch
call M2HOMEPOS2    :Back off stopper
call WAITM0        :Wait for the operation
call WAITM2        :Wait for stopper to home
call WAIT          :switch bounce?
call WAIT
call CHECK_STOP_H  :Stopper home OK?
call LINEAR_FOR    :Push linear feeder to eject part
call CHUCK_OPEN    :Open chuck
call WAITONE       :Wait two seconds
call M0TURN        :Position turning tool
```

```
call WAITM0      :Wait for cross slide
call CHECK_CROSS_H :Cross slide back?
call LINEAR_OFF   :Unload linear feeder
setb mes1
mov  a,#15
call DISPLAY
ret
```

FEED\_AND\_CHECK: :Feed part and check for stub (2 sec.)

```
clr  EA          :Stop all interrupts
clr  stub         :Clear stub bit
call LINEAR_FOR
call CHUCK_OPEN   :Open chuck
mov  r2,#255      :Load loop counter for 0.85 sec.
```

FEED\_AND\_CHECK3:

```
mov  r1,#255      :Load loop counter
```

FEED\_AND\_CHECK2:

```
call READ_STUB    :Read stub switch (9 ms)
jnz  FEED_AND_CHECK1 :Stub detected? (2 ms)
setb stub         :Set flag if so (1 ms)
```

FEED\_AND\_CHECK1:

```
djnz r1,FEED_AND_CHECK2 :Loop back (2 ms)
djnz r2,FEED_AND_CHECK3 :Loop back
call CHUCK_CLOSE    :Close the chuck
call WAITONE        :Wait for fully closed
call LINEAR_OFF
setb EA             :Restart interrupts
ret
```

LINEAR\_F\_BACK: :Pull linear feed back and check for problem

```
mov  error,#0      :clear error code
call LINEAR_BACK   :Move linear feeder back
mov  r3,#255       :reload loop counter for 1.7 sec
```

LINEAR\_F\_BACK3:

```
mov  r2,#200       :reload loop counter
```

LINEAR\_F\_BACK2:

```
mov  r1,#3         :reload loop counter (USE 2)
```

LINEAR\_F\_BACK1:

```
call READ_LINEAR_IN :Check back switch (9 ms)
jz   LINEAR_F_BACK0 :Get out if switch reached (2 ms)
djnz r1,LINEAR_F_BACK1 :(2 ms) Total loop time = 13 ms
djnz r2,LINEAR_F_BACK2
djnz r3,LINEAR_F_BACK3
mov  error,#11     :set error code if time expire
mov  p1,error      :set error display
```

LINEAR\_F\_BACK0:

```
call LINEAR_OFF    :Unload linear feeder
ret
```

LINEAR\_F\_FWD: :Linear forward feed and check for problem

```
mov  error,#10     :preset error code
call LINEAR_FOR     :Move linear feeder forward
mov  r3,#255       :reload loop counter for 1.7 sec
```

LINEAR\_F\_FWD3:

```
mov  r2,#255       :reload loop counter
```

LINEAR\_F\_FWD2:

```
mov  r1,#2         :reload loop counter (USE 2)
```

LINEAR\_F\_FWD1:

```
call READ_STUB     :Check back switch (9 ms)
jnz  LINEAR_F_FWD0 :clear error if switch reached (2 ms)
```

```
    mov     error,#0
LINEAR_F_FWD0:
    djnz    r1,LINEAR_F_FWD1 ;(2 ms) Total loop time = 13 ms
    djnz    r2,LINEAR_F_FWD2
    djnz    r3,LINEAR_F_FWD3
    ret

RUN1:      ;System run
    call    INISYS      ;Self test
RUN1C:
    call    CHUCK_MOTOR_ON
    call    WAITONE
    call    PART_FEED
    mov     pcount,#6
RUN1A:
    dec     pcount
    mov     a,pcount
    jnz     RUN1B
    setb    mes1
    mov     error,#14
    jmp     ALL_STOP
RUN1B:
    call    MAKE_SLIDE
    jnb     stub,RUN1A
    call    EJECT_STUB
    call    HOPPER_LAMP_OFF
    call    LINEAR_F_BACK
    jmp     RUN1C
    ret

TEST0:     ;Test routine for system parts
    call    WAITGO      ;Wait for go switch pressed
    call    READ_TEST    ;read test routine number
    rl      a            ;Multiply a by 2
    mov     DPTR,#JUMPTAB ;Point to jump table
    jmp     @a+DPTR      ;Jump to selected test routine

JUMPTAB:   ;Jump table for test routines
    ajmp    TEST00      ;Dummy routine
    ajmp    TEST1       ;Single piece test
    ajmp    TEST2       ;Turn slide test
    ajmp    TEST3       ;Cross slide test
    ajmp    TEST4       ;Stopper test
    ajmp    TEST5       ;Linear feeder test
    ajmp    TEST6       ;Rotary feeder test
    ajmp    TEST7       ;Chuck test
    ajmp    TEST8       ;Lathe motor test
    ajmp    TEST9       ;Tool set

TEST00:    ;Dummy subroutine
    ret

TEST1:     ;System cycle test
    call    INISYS      ;Self test
    call    WAITGO
TEST1C:
    call    CHUCK_MOTOR_ON
    call    HOPPER_LAMP_ON
    call    WAITONE
    call    PART_FEED
```

```
    mov    pcount,#6
TEST1A:
    dec    pcount
    mov    a,pcount
    jnz    TEST1B
    setb   mesl
    mov    error,#14
    jmp    ALL_STOP
TEST1B:
    call   MAKE_SLIDE
    jnb    stub.TEST1A
    call   EJECT_STUB
    call   HOPPER_LAMP_OFF
    call   LINEAR_F_BACK
    call   CHUCK_MOTOR_OFF
    call   WAITGO
    jmp    TEST1C
    ret
```

```
TEST2:      :Turning slide test
    call   ALARM_LAMP_OFF
    call   HOPPER_LAMP_ON
    call   M1HOME
    call   WAITM1
    call   WAIT
    call   M1TURN
    call   WAITM1
    call   WAIT
    call   M1HOME
    call   WAITM1
    call   WAIT
    call   HOPPER_LAMP_OFF
    call   CHECK_TURN_R
    mov    a,error
    jnz    TEST2_A
    ret
TEST2_A:
    call   ALARM_LAMP_ON
    ret
```

```
TEST3:      :Cross slide test
    call   ALARM_LAMP_OFF
    call   HOPPER_LAMP_ON
    call   M0HOME
    call   WAITM0
    call   WAIT
    call   M0CUT
    call   WAITM0
    call   WAIT
    call   M0TURN
    call   WAITM0
    call   HOPPER_LAMP_OFF
    call   CHECK_CROSS_H
    mov    a,error
    jnz    TEST3_A
    ret
TEST3_A:
    call   ALARM_LAMP_ON
    ret
```

```
TEST4      :Stopper test
call ALARM_LAMP_OFF
call HOPPER_LAMP_ON
call M2HOMEPOS3
call WAITM2
call WAIT
call M2POS1
call WAITM2
call WAIT
call M2HOMEPOS1
call WAITM2
call WAIT
call HOPPER_LAMP_OFF
call CHECK_STOP_R
mov  a.error
jnz  TEST4_A
ret
TEST4_A:
call ALARM_LAMP_ON
ret
```

```
TEST5:      :Linear feeder test
call ALARM_LAMP_OFF
call HOPPER_LAMP_ON
call LINEAR_F_FWD
call LINEAR_OFF
mov  a.error
jz   TEST5A
call ALARM_LAMP_ON
TEST5A:
call WAITONE
call ALARM_LAMP_OFF
call LINEAR_F_BACK
call LINEAR_OFF
mov  a.error
jz   TEST5B
call ALARM_LAMP_ON
TEST5B:
call HOPPER_LAMP_OFF
ret
```

```
TEST6:      :Rotary feeder test
call HOPPER_LAMP_ON
call ROTARY_GO
call WAITONE
call HOPPER_LAMP_OFF
ret
```

```
TEST7:      :Chuck test
call HOPPER_LAMP_ON
call CHUCK_CLOSE
call WAITONE
call WAITONE
call CHUCK_OPEN
call WAITONE
call WAITONE
call HOPPER_LAMP_OFF
ret
```

TEST8: :Lathe motor test  
call HOPPER\_LAMP\_ON  
call CHUCK\_MOTOR\_ON  
call WAITONE  
call WAITONE  
call CHUCK\_MOTOR\_OFF  
call HOPPER\_LAMP\_OFF  
ret

TEST9: :Tool set position  
call CHUCK\_OPEN  
call M0HOME  
call WAITM0  
call M1HOME  
call WAITM1  
call M2HOMEPOS3  
call WAITM2  
call M0CUT  
call WAITM0  
call M0TURN  
call WAITM0  
call M1SET  
call WAITM1  
call HOPPER\_LAMP\_ON  
call WAITGO  
call HOPPER\_LAMP\_OFF  
call CHUCK\_CLOSE  
call WAITONE  
call HOPPER\_LAMP\_ON  
call WAITGO  
call HOPPER\_LAMP\_OFF  
call M2POS1  
call WAITM2  
call HOPPER\_LAMP\_ON  
call WAITGO  
call HOPPER\_LAMP\_OFF  
call CHUCK\_OPEN  
call M2HOMEPOS1  
call WAITM2  
ret

M0HOME: :Home cross slide to reference position (T0 4 sec)  
mov m0sth,#high m0stroke :Load step counter high byte  
mov m0stl,#low m0stroke :Load step counter low byte  
mov relo0h,#high m0movrelo :Load timer reload high byte  
mov relo0l,#low m0movrelo :Load timer reload low byte  
mov phomef,#20 :set post home variable for no reverse  
mov phomeh,#0  
setb m0rev :set reverse bit  
clr m0tsel :select timer 0  
clr m0done :Go  
ret

M0\_OFF\_LIMIT: :Move cross slide off limit switch (T0 0.84 sec)  
mov m0sth,#0 :Load step counter high byte  
mov m0stl,#5 :Load step counter low byte  
mov relo0h,#high m0movrelo :Load timer reload high byte  
mov relo0l,#low m0movrelo :Load timer reload low byte  
clr m0rev :clear reverse bit

```
clr  m0tsel      ;select timer 0
clr  m0done      ;Go
ret
```

```
M0CUT:          ;Cut off operation (T0 8.82 sec)
mov  m0sth,#high m0fstroke ;Load step counter high byte
mov  m0stl,#low m0fstroke  ;Load step counter low byte
mov  relo0h,#high m0movrelo ;Load timer reload high byte
mov  relo0l,#low m0movrelo  ;Load timer reload low byte
clr  m0rev       ;clear reverse bit
clr  m0tsel      ;select timer 0
clr  m0done      ;Go
ret
```

```
M0TURN:         ;Move cross slide to turn position (T0 4.84 sec)
mov  m0sth,#high m0rstroke  ;Load step counter high byte
mov  m0stl,#low m0rstroke   ;Load step counter low byte
mov  phomeh,#high m0rstroke
mov  phomel,#low m0rstroke
call READ_DTRIM      ;Read trim switch, result in a
add  a,phomel        ;add trim to step counter low byte
mov  phomel,a        ;save the value
clr  a               ;clear a register
adde  a,phomeh       ;add any carry to high byte
mov  phomeh,a        ;save the value
mov  relo0h,#high m0movrelo ;Load timer reload high byte
mov  relo0l,#low m0movrelo  ;Load timer reload low byte
setb m0rev          ;set reverse bit
clr  m0tsel         ;select timer 0
clr  m0done         ;Go
ret
```

```
M1HOME:         ;Home turn slide (T1 11.0 sec)
mov  m1sth,#high m1rstroke  ;Load step counter high byte
mov  m1stl,#low m1rstroke   ;Load step counter low byte
mov  relo1h,#high m1movrelo ;Load timer reload high byte
mov  relo1l,#low m1movrelo  ;Load timer reload low byte
setb m1rev         ;set reverse bit
setb m1tsel        ;select timer 1
clr  m1done        ;Go
ret
```

```
M1SET:          ;Turn operation
mov  m1sth,#2         ;Load step counter high byte
mov  m1stl,#0         ;Load step counter low byte
mov  relo1h,#high m1cutrelo ;Load timer reload high byte
mov  relo1l,#low m1cutrelo  ;Load timer reload low byte
clr  m1rev           ;clear reverse bit
setb m1tsel          ;select timer 1
clr  m1done          ;Go
ret
```

```
M1TURN:         ;Turn operation (T1 11.8 sec)
mov  m1sth,#high m1fstroke  ;Load step counter high byte
mov  m1stl,#low m1fstroke   ;Load step counter low byte
mov  relo1h,#high m1cutrelo ;Load timer reload high byte
mov  relo1l,#low m1cutrelo  ;Load timer reload low byte
clr  m1rev           ;clear reverse bit
setb m1tsel          ;select timer 1
clr  m1done          ;Go
```

ret

M1TURN1: :Move turning tool to ready pos for facing (T0 10.6)

```
mov  m1sth.#high m1fstroke1 :Load step counter high byte
mov  m1stl.#low m1fstroke1  :Load step counter low byte
mov  relo1h.#high m1movrelo  :Load timer reload high byte
mov  relo1l.#low m1movrelo  :Load timer reload low byte
clr  m1rev          :clear reverse bit
clr  m1tsel         :select timer 0
clr  m1done         :Go
ret
```

M1TURN2: :Turning tool to clean up for facing (T0 1.2 sec)

```
mov  m1sth.#high m1fstroke2 :Load step counter high byte
mov  m1stl.#low m1fstroke2  :Load step counter low byte
mov  relo1h.#high m1cutrelo  :Load timer reload high byte
mov  relo1l.#low m1cutrelo  :Load timer reload low byte
clr  m1rev          :clear reverse bit
clr  m1tsel         :select timer 0
clr  m1done         :Go
ret
```

M2HOMEPOS1: :Home stopper from normal position (T0 2.4 sec)

```
mov  m2sth.#high m2rstroke1 :Load step counter high byte
mov  m2stl.#low m2rstroke1  :Load step counter low byte
mov  relo0h.#high m2movrelo  :Load timer reload high byte
mov  relo0l.#low m2movrelo  :Load timer reload low byte
setb m2rev          :set reverse bit
clr  m2tsel         :select timer 0
clr  m2done         :Go
ret
```

M2HOMEPOS2: :Home stopper from facing position (T1 7.8 sec)

```
mov  m2sth.#high m2rstroke2 :Load step counter high byte
mov  m2stl.#low m2rstroke2  :Load step counter low byte
mov  relo1h.#high m2movrelo  :Load timer reload high byte
mov  relo1l.#low m2movrelo  :Load timer reload low byte
setb m2rev          :set reverse bit
setb m2tsel         :select timer 1
clr  m2done         :Go
ret
```

M2HOMEPOS3: :Home stopper from clear chuck position (T1 8.4)

```
mov  m2sth.#high m2rstroke3 :Load step counter high byte
mov  m2stl.#low m2rstroke3  :Load step counter low byte
mov  relo1h.#high m2movrelo  :Load timer reload high byte
mov  relo1l.#low m2movrelo  :Load timer reload low byte
setb m2rev          :set reverse bit
setb m2tsel         :select timer 1
clr  m2done         :Go
ret
```

M2POS1: :Move stopper to normal position (T1 2.0 sec)

```
mov  m2sth.#high m2fstroke1 :Load step counter high byte
mov  m2stl.#low m2fstroke1  :Load step counter low byte
call READ_LTRIM           :Read trim switch, result in a
add  a,m2stl              :add trim to step counter low byte
```

```
mov    m2stl.a      :save the value
clr    a             :clear a register
addc   a,m2sth       :add any carry to high byte
mov    m2sth.a       :save the value
mov    relo1h,#high m2movrelo :Load timer reload high byte
mov    relo1l,#low m2movrelo :Load timer reload low byte
clr    m2rev         :clear reverse bit
setb   m2tsel        :select timer 1
clr    m2done        :Go
ret
```

```
M2POS2:      :Move stopper to facing position (T1 7.4 sec)
mov     m2sth,#high m2fstroke2 :Load step counter high byte
mov     m2stl,#low m2fstroke2  :Load step counter low byte
mov     relo1h,#high m2movrelo :Load timer reload high byte
mov     relo1l,#low m2movrelo  :Load timer reload low byte
clr     m2rev               :clear reverse bit
setb    m2tsel              :select timer 1
clr     m2done              :Go
ret
```

```
M2POS3:      :Move stopper to clear chuck of part (T1 8.0 sec)
mov     m2sth,#high m2fstroke3 :Load step counter high byte
mov     m2stl,#low m2fstroke3  :Load step counter low byte
mov     relo1h,#high m2movrelo :Load timer reload high byte
mov     relo1l,#low m2movrelo  :Load timer reload low byte
clr     m2rev               :clear reverse bit
setb    m2tsel              :select timer 1
clr     m2done              :Go
ret
```

```
STEP0:       :Timer0 interrupt service routine
clr     TR0              :Stop timer
mov     TL0,relo0l       :LSB timer reload
mov     TH0,relo0h       :MSB timer reload
setb    TR0              :Run timer
push    PSW              :Save program status word
push    DPL              :Save lower byte of data pointer
push    DPH              :Save high byte of data pointer
push    b                :Save b register
push    acc              :Save accumulator
call    READ_STOP        :Read stop switch
jnz     STEP07
setb    stopped          :If pressed, set flag
STEP07:
call    READ_E_STOP      :Read stop switch
jnz     STEP08
setb    estop            :If pressed, set flag
jmp     EMERGENCY_STOP
STEP08:
jb      m0tsel,STEP02     :This timer selected?
jb      m0done,STEP02     :Motor 0 done?
jb      m0rev,STEP01      :Reverse direction?
call    M0FORWARD         :Step forward
jmp     STEP02            :Done with motor 0
STEP01:
call    M0REVERSE         :Step back
STEP02:
```

```
jb    m1tsel.STEP03    :This timer selected?
jb    m1done.STEP03    :Motor 1 done?
jb    m1rev.STEP04     :Reverse direction?
call  M1FORWARD        :Step forward
jmp    STEP03          :Done with motor 1
STEP04:
call  M1REVERSE        :Step back
STEP03:
jb    m2tsel.STEP05    :This timer selected?
jb    m2done.STEP05    :Motor 2 done?
jb    m2rev.STEP06     :Reverse direction?
call  M2FORWARD        :Step forward
jmp    STEP05          :Done with motor 2
STEP06:
call  M2REVERSE        :Step back
STEP05:

STEP0DONE:
pop    acc              :Restore accumulator
pop    b                :Restore b register
pop    DPH              :Restore data pointer hi byte
pop    DPL              :Restore data pointer lo byte
pop    PSW              :Restore program status word
reti
```

```
STEP1      :Timer1 interrupt service routine
clr    TR1              :Stop timer
mov     TL1.relo1l      :LSB timer reload
mov     TH1.relo1h      :MSB timer reload
setb    TR1             :Run timer
push    PSW             :Save program status word
push    DPL             :Save lower byte of data pointer
push    DPH             :Save high byte of data pointer
push    b               :Save b register
push    acc             :Save accumulator
call    READ_STOP       :Read stop switch
jnz     STEP17
setb    stopped         :If pressed, set flag
STEP17:
call    READ_E_STOP     :Read stop switch
jnz     STEP18
setb    estop           :If pressed, set flag
jmp     EMERGENCY_STOP
STEP18:
jnb     m0tsel.STEP12   :This timer selected?
jb      m0done.STEP12   :Motor 0 done?
jb      m0rev.STEP11    :Reverse direction?
call    M0FORWARD       :Step forward
jmp     STEP12          :Done with motor 0
STEP11:
call    M0REVERSE       :Step back
STEP12:
jnb     m1tsel.STEP13   :This timer selected?
jb      m1done.STEP13   :Motor 1 done?
jb      m1rev.STEP14    :Reverse direction?
call    M1FORWARD       :Step forward
jmp     STEP13          :Done with motor 1
```

```
STEP14:
    call    M1REVERSE    ;Step back
STEP13:
    jnb     m2tsel.STEP15 ;This timer selected?
    jb      m2done.STEP15 ;Motor 2 done?
    jb      m2rev.STEP16 ;Reverse direction?
    call    M2FORWARD    ;Step forward
    jmp     STEP15        ;Done with motor 2
STEP16:
    call    M2REVERSE    ;Step back
STEP15:
STEP1DONE:
    pop     acc           ;Restore accumulator
    pop     b             ;restore b register
    pop     DPH           ;Restore data pionter hi byte
    pop     DPL           ;Restore data pointer lo byte
    pop     PSW           ;Restore program status word
    ret

M0FORWARD:    ;Cross slide move forward
    mov     a,m0stl       ;load lsb of step counter
    jnz     M0FORWARD0
    mov     a,m0sth       ;load msb of step counter
    jnz     M0FORWARD0
    setb    m0done
    clr     m0speed
    mov     DPTR,#aport1  ;point to motor port address
    movx    a,@DPTR       ;read port value
    orl     a,#0Fh        ;mask lower nibble
    movx    @DPTR,a        ;send it to motor
    ret

M0FORWARD0:
    call    READ_CUT_HOME ;check limit switch
    jz      M0FORWARD2    ;do not decrement step count if pressed
    mov     a,m0stl       ;check for speed change point
    cjne    a,#low m0begincut,M0FORWARD3
    mov     a,m0sth
    cjne    a,#high m0begincut,M0FORWARD3
    mov     relo0h,#high m0cutrelo
    mov     relo0l,#low m0cutrelo
    setb    m0speed

M0FORWARD3:
    jnb     m0speed.M0FORWARD4
    clr     c              ;Increase speed of cross slide
    mov     a,relo0l       ;load lsb of step counter
    add     a,#1           ;increment lsb
    mov     relo0l,a       ;return the value
    mov     a,relo0h       ;load msb
    adde    a,#0           ;add carry flag if any
    mov     relo0h,a       ;return value

M0FORWARD4:
    clr     c              ;clear carry flag
    mov     a,m0stl       ;load lsb of step counter
    subb    a,#1           ;decrement lsb
    mov     m0stl,a        ;return the value
    mov     a,m0sth       ;load msb
```

```
    subb    a,#0          :subtract carry flag if any
    mov     m0sth,a        :return value
M0FORWARD2:
    inc     m0ph           :increment phase counter
    mov     a,m0ph
    cjne    a,#8,M0FORWARD1
    mov     a,#0           :reset phase counter
    mov     m0ph,a

M0FORWARD1:
    mov     DPTR,#STEPTAB12F :point to phase table
    move    a,@a+DPTR      :read it
    mov     b,a            :save phase pattern in b
    mov     DPTR,#aport1    :point to motor port address
    movx    a,@DPTR        :read port value
    and     a,#0F0h        :mask lower nibble
    orl     a,b            :move bit pattern to lower nibble
    movx    @DPTR,a        :send it to motor
    ret

M0REVERSE:    :Cross slide move backward
    jb      holdm0,M0REVERSE4 :check hold mode
    jb      m0dbo,M0REVERSE2
    call    READ_CUT_HOME    :check limit switch
    jz      M0REVERSE2      :go to post limit if pressed
    mov     a,m0stl        :load lsb of step counter
    jnz     M0REVERSE0
    mov     a,m0sth        :load msb of step counter
    jnz     M0REVERSE0
M0REVERSE2:    :post limit movement
    call    TURN_POS_SW
    jz      M0REVERSE6
    setb    m0dbo          :set debounce bit
    mov     relo0h,#high m0limrelo : *
    mov     relo0l,#low m0limrelo  : *
    clr     c              :clear carry flag
    mov     a,phome1       :load lsb of step counter
    subb    a,#1           :decrement lsb
    mov     phome1,a        :return the value
    mov     a,phomeh       :load msb
    subb    a,#0           :subtract carry flag if any
    mov     phomeh,a        :return value
    mov     a,phome1       :load lsb of step counter
    jnz     M0REVERSE3
    mov     a,phomeh       :load msb of step counter
    jnz     M0REVERSE3
M0REVERSE6:
    mov     m0hold,#10     :Hold still after stop
    setb    holdm0
    ret
M0REVERSE4:
    dec     m0hold
    mov     a,m0hold
    jz      M0REVERSE5
    ret
```

```
M0REVERSE5:
    clr    m0dbo
    clr    holdm0
    setb    m0done
    mov     DPTR,#aport1    ;point to motor port address
    movx    a, a DPTR        ;read port value
    orl     a,#0Fh          ;mask lower nibble
    movx    a DPTR,a        ;send it to motor
    ret
```

```
M0REVERSE0:
    clr     c                ;clear carry flag
    mov     a,m0stl          ;load lsb of step counter
    subb    a,#1             ;decrement lsb
    mov     m0stl,a          ;return the value
    mov     a,m0sth          ;load msb
    subb    a,#0             ;subtract carry flag if any
    mov     m0sth,a          ;return value
```

```
M0REVERSE3:
    dec     m0ph             ;decrement phase counter
    mov     a,m0ph
    cjne    a,#0FFh,M0REVERSE1
    mov     a,#7             ;reset phase counter
    mov     m0ph,a
```

```
M0REVERSE1:
    mov     DPTR,#STEPTAB12F ;point to phase table
    movc    a, a+DPTR        ;read it
    mov     b,a              ;save phase pattern in b
    mov     DPTR,#aport1    ;point to motor port address
    movx    a, a DPTR        ;read port value
    anl     a,#0F0h          ;mask lower nibble
    orl     a,b              ;move bit pattern to lower nibble
    movx    a DPTR,a        ;send it to motor
    ret
```

```
M1FORWARD:    ;Turn slide move forward
    mov     a,m1stl          ;load lsb of step counter
    jnz     M1FORWARD0
    mov     a,m1sth          ;load msb of step counter
    jnz     M1FORWARD0
    setb    m1done
    mov     DPTR,#aport1    ;point to motor port address
    movx    a, a DPTR        ;read port value
    orl     a,#0F0h          ;mask upper nibble
    movx    a DPTR,a        ;send it to motor
    ret
```

```
M1FORWARD0:
    call    READ_TURN_HOME  ;check limit switch
    jz      M1FORWARD2      ;do not decrement step count if pressed
    clr     c                ;clear carry flag
    mov     a,m1stl          ;load lsb of step counter
    subb    a,#1             ;decrement lsb
    mov     m1stl,a          ;return the value
    mov     a,m1sth          ;load msb
    subb    a,#0             ;subtract carry flag if any
    mov     m1sth,a          ;return value
```

M1FORWARD2:

```
inc    m1ph      :increment phase counter
mov     a,m1ph
cjne    a,#4,M1FORWARD1
mov     a,#0      :reset phase counter
mov     m1ph,a
```

M1FORWARD1:

```
mov     DPTR,#STEPTAB2R :point to phase table
movc    a,@a+DPTR      :read it
swap    a              :swap nibbles
mov     b,a            :save phase pattern in b
mov     DPTR,#aport1   :point to motor port address
movx    a,@DPTR        :read port value
anl     a,#0Fh         :mask upper nibble
orl     a,b            :move bit pattern to lower nibble
movx    @DPTR,a        :send it to motor
ret
```

MIREVERSE: :Turn slide move backward

```
call    READ_TURN_HOME :check limit switch
jz      MIREVERSE2      :done if pressed
mov     a,m1stl         :load lsb of step counter
jnz     MIREVERSE0
mov     a,m1sth         :load msb of step counter
jnz     MIREVERSE0
```

MIREVERSE2:

```
setb    m1done
mov     DPTR,#aport1   :point to motor port address
movx    a,@DPTR        :read port value
orl     a,#0F0h        :mask upper nibble
movx    @DPTR,a        :send it to motor
ret
```

MIREVERSE0:

```
clr     c              :clear carry flag
mov     a,m1stl         :load lsb of step counter
subb    a,#1            :decrement lsb
mov     m1stl,a         :return the value
mov     a,m1sth         :load msb
subb    a,#0            :subtract carry flag if any
mov     m1sth,a         :return value
dec     m1ph            :decrement phase counter
mov     a,m1ph
cjne    a,#0FFh,MIREVERSE1
mov     a,#3            :reset phase counter
mov     m1ph,a
```

MIREVERSE1:

```
mov     DPTR,#STEPTAB2R :point to phase table
movc    a,@a+DPTR      :read it
swap    a              :swap nibbles
mov     b,a            :save phase pattern in b
mov     DPTR,#aport1   :point to motor port address
movx    a,@DPTR        :read port value
anl     a,#0Fh         :mask upper nibble
orl     a,b            :move bit pattern to lower nibble
movx    @DPTR,a        :send it to motor
ret
```

```
M2FORWARD:    :Stopper move forward
    mov     a,m2stl    :load lsb of step counter
    jnz     M2FORWARD0
    mov     a,m2sth    :load msb of step counter
    jnz     M2FORWARD0
    setb    m2done
    mov     DPTR,#aport2 :point to motor port address
    movx    a,@DPTR    :read port value
    orl     a,#0Fh     :mask lower nibble
    movx    @DPTR,a    :send it to motor
    ret

M2FORWARD0:
    call    READ_STOP_HOME :check limit switch
    jz      M2FORWARD2    :do not decrement step count if pressed
    clr     c          :clear carry flag
    mov     a,m2stl    :load lsb of step counter
    subb    a,#1       :decrement lsb
    mov     m2stl,a    :return the value
    mov     a,m2sth    :load msb
    subb    a,#0       :subtract carry flag if any
    mov     m2sth,a    :return value

M2FORWARD2:
    inc     m2ph       :increment phase counter
    mov     a,m2ph
    cjne    a,#4,M2FORWARD1
    mov     a,#0       :reset phase counter
    mov     m2ph,a

M2FORWARD1:
    mov     DPTR,#STEPTAB2R :point to phase table
    mov     a,@a+DPTR    :read it
    mov     b,a         :save phase pattern in b
    mov     DPTR,#aport2 :point to motor port address
    movx    a,@DPTR    :read port value
    anl     a,#0F0h     :mask lower nibble
    orl     a,b         :move bit pattern to lower nibble
    movx    @DPTR,a    :send it to motor
    ret

M2REVERSE:    :Stopper move reverse
    call    READ_STOP_HOME :check limit switch
    jz      M2REVERSE2    :done if pressed
    mov     a,m2stl    :load lsb of step counter
    jnz     M2REVERSE0
    mov     a,m2sth    :load msb of step counter
    jnz     M2REVERSE0
M2REVERSE2:
    setb    m2done
    mov     DPTR,#aport2 :point to motor port address
    movx    a,@DPTR    :read port value
    orl     a,#0Fh     :mask lower nibble
    movx    @DPTR,a    :send it to motor
    ret
M2REVERSE0:
    clr     c          :clear carry flag
    mov     a,m2stl    :load lsb of step counter
    subb    a,#1       :decrement lsb
    mov     m2stl,a    :return the value
    mov     a,m2sth    :load msb
    subb    a,#0       :subtract carry flag if any
```

```

mov    m2sth,a      :return value
dec    m2ph         :decrement phase counter
mov    a,m2ph
cjne   a,#0FFh,M2REVERSE1
mov    a,#3         :reset phase counter
mov    m2ph,a
M2REVERSE1:
mov    DPTR,#STEPTAB2R :point to phase table
move   a,@a+DPTR     :read it
mov    b,a          :save phase pattern in b
mov    DPTR,#aport2  :point to motor port address
movx   a,@DPTR       :read port value
anl    a,#0F0h       :mask lower nibble
orl    a,b           :move bit pattern to lower nibble
movx   @DPTR,a       :send it to motor
ret

```

```

INI8255:          :Initiate 8255 PPI chip
call   WAITONE     :wait a bit
mov    DPTR,#rport1 :point to control register of 8255-1
mov    a,#89h       :A out, B out, C in
movx   @DPTR,a      :send program byte
mov    DPTR,#rport2 :point to control register of 8255-2
mov    a,#8Bh       :A out, B in, C in
movx   @DPTR,a      :send program byte
call   WAIT         :wait a bit
mov    DPTR,#aport1 :point to stepper motor port
mov    a,#0FFh      :Clear stepper port
movx   @DPTR,a
mov    DPTR,#aport2 :point to stepper motor port
mov    a,#0Fh       :Clear stepper port
movx   @DPTR,a
ret

```

```

INIVARS:          :Initiate system variables
mov    m0ph,#0      :Initiate phase counter motor 0
mov    m1ph,#0      :Initiate phase counter motor 1
mov    m2ph,#0      :Initiate phase counter motor 2
setb   m0done        :stop motor 0
setb   m1done        :stop motor 1
setb   m2done        :stop motor 2
clr    holdm0        :clear motor 0 hold bit
clr    m0speed       :clear motor 0 speed up bit
clr    m0dbo         :clear motor 0 switch debounce bit
clr    m0rev         :clear motor 0 reverse direction
clr    m1rev         :clear motor 1 reverse direction
clr    m2rev         :clear motor 2 reverse direction
mov    relo0h,#0     :clear high byte timer0 reload value
mov    relo0l,#0     :clear low byte timer0 reload value
mov    relo1h,#0     :clear high byte timer1 reload value
mov    relo1l,#0     :clear low byte timer1 reload value
ret

```

```

INICLOCK:         :Initiate timer interrupt
clr    T0           :Disable input to timer 0
clr    T1           :Disable input to timer 1
mov    TMOD,#11h    :Timer/counter 0&1 as timer mode 1
setb   TR0          :Run clock 0
setb   TR1          :Run clock 1
setb   ET0          :Enable timer 0 interrupt

```

```
setb  ETI      ;Enable timer 1 interrupt
setb  EA       ;Enable master interrupt switch
ret
```

```
STEP_POWER_ON: ;Turn on step motor power supply
mov  DPTR,#bport1 ;point to stepper power control port
movx a,@DPTR      ;read port
orl  a,#00000001b ;set control bit
movx @DPTR,a      ;send control bit
ret
```

```
STEP_POWER_OFF: ;Turn off step motor power supply
mov  DPTR,#bport1 ;point to stepper power control port
movx a,@DPTR      ;read port
and  a,#11111110b ;clear control bit
movx @DPTR,a      ;send control bit
ret
```

```
HYD_POWER_ON: ;Turn on hydraulic power unit
mov  DPTR,#bport1 ;point to hydraulic power control port
movx a,@DPTR      ;read port
orl  a,#00100000b ;set control bit
movx @DPTR,a      ;send control bit
ret
```

```
HYD_POWER_OFF: ;Turn off hydraulic power unit
mov  DPTR,#bport1 ;point to hydraulic power control port
movx a,@DPTR      ;read port
and  a,#11011111b ;clear control bit
movx @DPTR,a      ;send control bit
ret
```

```
CHUCK_MOTOR_ON: ;Turn on lathe motor
mov  DPTR,#bport1 ;point to lathe motor control port
movx a,@DPTR      ;read port
orl  a,#01000000b ;set control bit
movx @DPTR,a      ;send control bit
ret
```

```
CHUCK_MOTOR_OFF: ;Turn off lathe motor
mov  DPTR,#bport1 ;point to lathe motor control port
movx a,@DPTR      ;read port
and  a,#10111111b ;clear control bit
movx @DPTR,a      ;send control bit
ret
```

```
CHUCK_OPEN: ;Open chuck
mov  DPTR,#bport1 ;point to chuck hydraulic control port
movx a,@DPTR      ;read port
orl  a,#00010000b ;set control bit
movx @DPTR,a      ;send control bit
ret
```

```
CHUCK_CLOSE: ;Close chuck
mov  DPTR,#bport1 ;point to chuck hydraulic control port
movx a,@DPTR      ;read port
and  a,#11101111b ;clear control bit
movx @DPTR,a      ;send control bit
ret
```

```
LINEAR_FOR:    ;Move linear feeder forward
    mov     DPTR,#bport1    ;point to linear feeder control port
    movx    a, @DPTR        ;read port
    anl     a,#11111011b    ;make sure linear back is off
    orl     a,#00001000b    ;set control bit of feeder
    movx    @DPTR,a         ;send control bit
    ret
```

```
LINEAR_BACK:   ;Move linear feeder back
    mov     DPTR,#bport1    ;point to linear feeder control port
    movx    a, @DPTR        ;read port
    anl     a,#11110111b    ;make sure linear forward is off
    orl     a,#00001000b    ;set control bit of feeder
    movx    @DPTR,a         ;send control bit
    ret
```

```
LINEAR_OFF:    ;Release air pressure in linear feeder
    mov     DPTR,#bport1    ;point to linear feeder control port
    movx    a, @DPTR        ;read port
    anl     a,#11110011b    ;linear forward & backward bits off
    movx    @DPTR,a         ;send control bits
    ret
```

```
ROTARY_GO:     ;Activate rotary feeder
    mov     DPTR,#bport1    ;point to rotary feeder control port
    movx    a, @DPTR        ;read port
    orl     a,#00000010b    ;set control bit
    movx    @DPTR,a         ;send control bit
    call    WAIT            ;delay a bit
    call    WAIT
    anl     a,#11111011b    ;clear control bit
    movx    @DPTR,a         ;send control bit
    ret
```

```
READY_LAMP_ON: ;Turn on ready lamp
    mov     DPTR,#bport1    ;point to ready lamp control port
    movx    a, @DPTR        ;read port
    orl     a,#10000000b    ;set control bit
    movx    @DPTR,a         ;send control bit
    ret
```

```
READY_LAMP_OFF: ;Turn off ready lamp
    mov     DPTR,#bport1    ;point to ready lamp control port
    movx    a, @DPTR        ;read port
    anl     a,#01111111b    ;clear control bit
    movx    @DPTR,a         ;send control bit
    ret
```

```
HOPPER_LAMP_ON: ;Turn on hopper empty lamp
    mov     DPTR,#aport2     ;point to hopper lamp control port
    movx    a, @DPTR        ;read port
    orl     a,#00010000b    ;set control bit
    movx    @DPTR,a         ;send control bit
    ret
```

```
HOPPER_LAMP_OFF: ;Turn off hopper empty lamp
    mov     DPTR,#aport2     ;point to hopper lamp control port
    movx    a, @DPTR        ;read port
    anl     a,#11101111b    ;clear control bit
    movx    @DPTR,a         ;send control bit
    ret
```

ALARM\_LAMP\_ON: :Turn on remote alarm

```
mov DPTR,#aport2 :point to alarm lamp control port
movx a,@DPTR :read port
orl a,#01100000b :set control bit
movx @DPTR,a :send control bit
ret
```

ALARM\_LAMP\_OFF: :Turn off remote alarm

```
mov DPTR,#aport2 :point to alarm lamp control port
movx a,@DPTR :read port
anl a,#10011111b :clear control bit
movx @DPTR,a :send control bit
ret
```

READ\_DTRIM: :Read diameter trim, result in acc

```
mov DPTR,#bport2 :point to diameter trim port
movx a,@DPTR :read port
orl a,#0F0h :mask upper nibble
cpl a :invert bits
ret
```

READ\_LTRIM: :Read length trim, result in acc

```
mov DPTR,#bport2 :point to length trim port
movx a,@DPTR :read port
orl a,#0Fh :mask lower nibble
swap a :swap nibbles
cpl a :invert bits
ret
```

READ\_TEST: :Read test code, result in acc

```
mov DPTR,#cport2 :point to test switch port
movx a,@DPTR :read port
orl a,#0F0h :mask upper nibble
cpl a :invert bits
mov r0,a :Make sure a <= 9
clr c
mov a,#9
subb a,r0
jbc cy,READ_TEST0
mov a,r0
ret
```

READ\_TEST0:

```
clr a
ret
```

READ\_GO: :Read Go switch, a=0 if pressed

```
mov DPTR,#cport2 :point to go switch port
movx a,@DPTR :read port
anl a,#00010000b :If not pressed
jnz READ_GO1
ret
```

READ\_GO1:

```
mov DPTR,#cport1 :point to go switch port
movx a,@DPTR :read port
anl a,#10000000b :If not pressed
ret
```

READ\_STOP: :Read stop switch, a=0 if pressed

```
mov DPTR,#cport2 :point to stop switch port
```

```
movx a, @DPTR    ;read port
anl a, #00100000b ;a = 0 if pressed
ret
```

```
READ_E_STOP: ;Read emergency sw, a=0 if pressed
mov DPTR, #cport2 ;point to stop switch port
movx a, @DPTR    ;read port
anl a, #01000000b ;a = 0 if pressed
ret
```

```
READ_HOPPER: ;Read hopper empty sw, a=1 if empty
mov DPTR, #cport1 ;point to hopper switch port
movx a, @DPTR    ;read port
anl a, #00000001b ;a = 1 if empty
ret
```

```
READ_LINEAR_IN: ;Read linear feed sw, a=0 if full in
mov DPTR, #cport1 ;point to linear in switch port
movx a, @DPTR    ;read port
anl a, #00000010b ;a = 0 if full in
ret
```

```
READ_STUB: ;Read stub sw, a=0 if stub reached
mov DPTR, #cport1 ;point to stub switch port
movx a, @DPTR    ;read port
anl a, #00000100b ;a = 0 if at stub
ret
```

```
READ_TURN_HOME: ;Read turn slide home, a=0 for home
mov DPTR, #cport1 ;point to turn slide home switch port
movx a, @DPTR    ;read port
anl a, #00001000b ;a = 0 if home
ret
```

```
READ_CUT_HOME: ;Read cut slide home, a=0 for home
mov DPTR, #cport1 ;point to cut slide home switch port
movx a, @DPTR    ;read port
anl a, #00010000b ;a = 0 if home
ret
```

```
READ_STOP_HOME: ;Read stopper home, a=0 for home
mov DPTR, #cport1 ;point to stop slide home switch port
movx a, @DPTR    ;read port
anl a, #00100000b ;a = 0 if home
ret
```

```
TURN_POS_SW: ;Read turn position sw, a=0 for pressed
mov DPTR, #cport1 ;point to turn position switch port
movx a, @DPTR    ;read port
anl a, #01000000b ;a = 0 if home
ret
```

```
WAITSW: ;Wait for front panel switch
call READ_GO
jz WAITSW_DONE
call READ_STOP
jnz WAITSW
setb stopped
WAITSW_DONE.
ret
```

WAITGO: ;Wait for GO switch to be pressed

```
setb  mes1
mov   a,#5
call  DISPLAY
```

WAITGO1:

```
call  READ_GO      ;Read go switch
jnz   WAITGO1      ;Wait around
setb  mes1
mov   a,#15
call  DISPLAY
ret
```

WAITM0: ;Wait for motor 0 done

```
jnb   m0done,WAITM0 ;wait until done
ret
```

WAITM1: ;Wait for motor 1 done

```
jnb   m1done,WAITM1 ;wait until done
ret
```

WAITM2: ;Wait for motor 2 done

```
jnb   m2done,WAITM2 ;wait until done
ret
```

WAITONE: ;Time delay one second

```
mov   r3,#10
WAITONE1:
call  WAIT
djnz  r3,WAITONE1
ret
```

WAIT: ;Time delay subroutine 100 millisecc

```
mov   r1,#196
WAIT1:
mov   r2,#0FFh
WAIT2:
djnz  r2,WAIT2
djnz  r1,WAIT1
ret
```

CHECK\_CROSS\_R: ;Check cross slide reversal for error

```
mov   a,m0sth      ;load step counter MSB
jnz   CHECK_CROSS_R1 ;error if not zero
mov   a,m0stl      ;load step counter LSB
jz    CHECK_CROSS_R2 ;If zero, limit switch not reached
clr   c            ;clear carry flag
subb  a,#200       ;subtract 200
jnb   cy,CHECK_CROSS_R1 ;error if more than 200
mov   error,#0
ret
```

CHECK\_CROSS\_R1: ;Slide reach limit too soon

```
mov   error,#2
jmp   ALL_STOP
```

CHECK\_CROSS\_R2: ;Limit not reached

```
mov   error,#3
jmp   ALL_STOP
```

CHECK\_CROSS\_F: ;Check cross slide forward for error

```
call READ_CUT_HOME
jz CHECK_CROSS_F1
mov error,#0
ret
CHECK_CROSS_F1:
mov error,#1
jmp ALL_STOP
```

```
CHECK_CROSS_H: ;Check cross slide for proper homeing
call WAIT ;Limit switch debounce
call READ_CUT_HOME
jnz CHECK_CROSS_H1
mov error,#0
ret
CHECK_CROSS_H1:
mov error,#3
jmp ALL_STOP
```

CHECK\_TURN\_R: ;Check turn slide reversal for error  
Appendix B. Firmware Program Listing (continue).

```
mov a,m1sth ;load step counter MSB
jnz CHECK_TURN_R1 ;error if not zero
mov a,m1stl ;load step counter LSB
jz CHECK_TURN_R2 ;If zero, limit sw not reached
clr c ;clear carry flag
subb a,#200 ;subtract 200
jnb cy,CHECK_TURN_R1;error if more than 200
mov error,#0
ret
CHECK_TURN_R1: ;Slide reach limit too soon
mov error,#5
jmp ALL_STOP
CHECK_TURN_R2: ;Limit not reached
mov error,#6
jmp ALL_STOP
```

```
CHECK_TURN_F: ;Check turn slide forward for error
call READ_TURN_HOME
jz CHECK_TURN_F1
mov error,#0
ret
CHECK_TURN_F1:
mov error,#4
jmp ALL_STOP
```

```
CHECK_TURN_H: ;Check turn slide for proper homeing
call WAIT ;Limit switch debounce
call READ_TURN_HOME
jnz CHECK_TURN_H1
mov error,#0
ret
CHECK_TURN_H1:
mov error,#6
jmp ALL_STOP
```

```
CHECK_STOP_R: :Check stopper slide reversal for error
    mov     a,m2sth      :load step counter MSB
    jnz     CHECK_STOP_R1 :error if not zero
    mov     a,m2stl      :load step counter LSB
    jz      CHECK_STOP_R2 :If zero, limit sw not reached
    clr     c            :clear carry flag
    subb    a,#200       :subtract 200
    jnb     cy,CHECK_STOP_R1:error if more than 200
    mov     error,#0
    ret
CHECK_STOP_R1:          :Slide reach limit too soon
    mov     error,#8
    jmp     ALL_STOP
CHECK_STOP_R2:          :Limit not reached
    mov     error,#9
    jmp     ALL_STOP
```

```
CHECK_STOP_F: :Check stop slide forward for error
    call    READ_STOP_HOME
    jz      CHECK_STOP_F1
    mov     error,#0
    ret
CHECK_STOP_F1:
    mov     error,#7
    jmp     ALL_STOP
```

```
CHECK_STOP_H: :Check stopper for proper homing
    call    WAIT         :Limit switch debounce
    call    READ_STOP_HOME
    jnz     CHECK_STOP_H1
    mov     error,#0
    ret
CHECK_STOP_H1:
    mov     error,#9
    jmp     ALL_STOP
```

```
CHECK_LINEAR_B: :Check linear feeder full back position
    mov     a,error
    jnz     ALL_STOP
    ret
```

```
HOPPER_EMPTY: :Hopper empty condition
    call    HOPPER_LAMP_ON
    mov     a,error
    call    DISPLAY
    call    CHUCK_MOTOR_OFF :Turn off lathe motor
    call    STEP_POWER_OFF :Turn off step motor power
    call    LINEAR_F_BACK   :Pull back linear feeder
    call    LINEAR_OFF      :Unload linear feeder
    call    CHUCK_OPEN      :Open chuck
HOPPER_EMPTY_1:
    call    HOPPER_LAMP_OFF :Flash hopper lamp
    call    WAIT
    call    WAIT
    call    HOPPER_LAMP_ON
    call    WAIT
    call    WAIT
    call    WAIT
    call    WAIT
    jmp     HOPPER_EMPTY_1 :Loop forever, wait for reset
```



```
db 00001001b
db 00000011b
db 00000110b
```

STEPTAB2R: :2 phase drive reverse bit pattern

```
db 00001100b
db 00000110b
db 00000011b
db 00001001b
```

STEPTAB12R: :1-2 phase drive reverse bit pattern

```
db 00001100b
db 00001110b
db 00000110b
db 00000111b
db 00000011b
db 00001011b
db 00001001b
db 00001101b
```

STEPTAB12F: :1-2 phase drive forward bit pattern

```
db 00001100b
db 00001101b
db 00001001b
db 00001011b
db 00000011b
db 00000111b
db 00000110b
db 00001110b
```

:LCD Driver written by Somchai Pattana

:call INIT\_LCD to initialize LCD

:call DISPLAY with message number in a

```
delay:          :delay 15 millisecc
    mov r1,#15
WAITLCD1:       :delay 1 millisecc
    mov r2,#226  :[(12 x (1/11.0592 MHz))] x [(4x226)+2]
WAITLCD2:
    nop          := 983.0729 microsec
    nop
    djnz r2,WAITLCD2
    nop
    nop
    djnz r1,WAITLCD1 :Loop 15 time
    ret
```

LCD\_DONE:

```
    mov r1,#210 :1700 u sec max
```

LCD\_DONE1:

```
    mov DPTR,#rd_busy :Point to LCD busy instruction
    movx a,@DPTR       :Read port
    jnb ACC.7,LCD_DONE2 :Wait until bit 7 is zero
    djnz r1,LCD_DONE1
```

LCD\_DONE2:

```
    ret
```

ClrScr:

```
    call LCD_DONE      :Wait until LCD done
```

```
    mov DPTR,#wr_inst :Point to LCD write instruction
```

```
    mov a,#01h      :Set clear data to A
    movx @DPTR,a    :Send clear screen data
    ret
Init_LCD:
    call delay
    mov DPTR,#wr_inst :Point to LCD write instruction
    mov a,#30h      :8 bit interface set
    movx @DPTR,a    :Send function set
    call delay
    mov DPTR,#wr_inst :Point to LCD write instruction
    mov a,#30h      :8 bit interface set
    movx @DPTR,a    :Send function set
    call delay
    mov DPTR,#wr_inst :Point to LCD write instruction
    mov a,#30h      :8 bit interface set
    movx @DPTR,a    :Send function set
    call LCD_DONE    :Wait until LCD done
    mov DPTR,#wr_inst :Point to LCD write instruction
    mov a,#38h      :8 bits data, 16 columns, 5x7 dots
    movx @DPTR,a    :Send function set
    call LCD_DONE    :Wait until LCD done
    mov DPTR,#wr_inst :Point to LCD write instruction
    mov a,#08h      :Display off
    movx @DPTR,a    :Send display control

    call ClrScr      :Clear all display

    call LCD_DONE    :Wait until LCD done
    mov DPTR,#wr_inst :Point to LCD write instruction
    mov a,#0Eh      :Display on, cursor on, blink off
    movx @DPTR,a    :Send display control
    ret

Display:
    mov r6,a        :Move data to R6
    call ClrScr      :Clear display
    mov a,r6        :Move data to ACC
    jnz SHOW        :Return if code 0
    ret
SHOW:
    dec a           :Match data to table
    swap a          :Swap nibbles
    mov r6,a        :Move data to R6
    mov r5,#80h     :First DD RAM address
    mov r7,#10h     :Load number of character
NEXT_CHR:
    call LCD_DONE    :Wait until LCD done
    jb mes1,NEXT_CHR1
    mov DPTR,#MESSAGE :Point to string table
    jmp NEXT_CHR2
NEXT_CHR1:
    mov DPTR,#MESSAGE1
NEXT_CHR2:
    mov a,r6        :Move string position to ACC
    move a,a+DPTR    :Read ASCII from table
    mov DPTR,#wr_data :Point to LCD write data port
    movx @DPTR,a    :Send data
    inc r5          :Increase DD RAM address
    cjne r5,#88h,NEXT :Check last 8 digit
    mov r5,#0C0h    :Set the 8th digit DD RAM address
```

```
call LCD_DONE      ;Wait until LCD done
mov DPTR,#wr_inst  ;Point to LCD write instruction
mov a,r5           ;Set DD RAM address
movx @DPTR,a       ;Send function set
NEXT:
inc r6             ;Increase string position
djnz r7,NEXT_CHR   ;Check last character
clr mesl
ret
```

MESSAGE: ;Table of error message

```
db '01 CROSS LIMIT '
db '02 CROSS STROKE '
db '03 CROSS NOT RET'
db '04 TURN LIMIT '
db '05 TURN STROKE '
db '06 TURN NOT RET '
db '07 STOPPER LIMIT'
db '08 STOP STROKE '
db '09 STOP NOT RET '
db '10 CHUCK NOT CLR'
db '11 LINEAR NOT RE'
db '12 ROTARY PROB. '
db '13 HOPPER EMPTY '
db '14 EMERGENCY ST '
db '15 STOPPED ' '
```

MESSAGE1: ;Table of display message

```
db 'INITIALIZING '
db 'FEEDING NEW PART'
db 'MACHINING SLIDE '
db 'EJECTING STUB '
db 'READY--PRESS GO '
db '6 '
db '7 '
db '8 '
db '9 '
db '10 '
db '11 '
db '12 '
db '13 '
db '16 COUNT ERROR '
db ' ' '
```

end

## Appendix C. Specifications.

The single purpose lathe is a manual lathe retrofitted for automated machining of the first stage slider production. The cycle time is 40 seconds per piece and the tool change is 120 pieces for turning and 200 pieces for cut off. The lathe being used is YAM-550 engine lathe with the following specifications:

### Cross slide

pitch 4 mm/rev.  
forward stroke 15 mm.  
reverse stroke 16 mm.  
turn stroke 3.35 mm.  
motor resolution 400 steps/rev.

### Top slide

pitch 3 mm/rev.  
forward stroke 30 mm.  
reverse stroke 31 mm.  
ready for facing 27 mm.  
turn for facing 3 mm.  
motor resolution 200 steps/rev.

### Stopper slide

pitch 4 mm/rev.  
normal stroke 10 mm.  
return from normal 12 mm.  
facing stroke 37 mm.  
return from facing 39 mm.  
clear chuck stroke 40 mm.  
return from clear 42 mm.  
motor resolution 200 steps/rev.

**Appendix D. Cost Breakdown.**

| Description                     | Part No.          | Vender    | Quan. | a       | Total          | Delivery   |
|---------------------------------|-------------------|-----------|-------|---------|----------------|------------|
| <b>CONTROL UNIT</b>             |                   |           |       |         |                |            |
| Front control panel             | custom            | CCR       | 1     | 1,500   | 1,500          | 7 days     |
| Microprocessor board            | ANT-32 Sila       |           | 1     | 1,590   | 1,590          | 3 days     |
| EPROM                           | 27128 CCR         |           | 1     | 200     | 200            | in stock   |
| Stepper motor driver            | EX-STEPM          | Sila      | 3     | 650     | 1,950          | 3 days     |
| Relay output board              | EX-RELAY          | Sila      | 3     | 650     | 1,950          | 3 days     |
| Input board                     | custom            | CCR       | 1     | 300     | 300            | 3 days     |
| Power supply                    | 5V3A,24V1A POW-53 | Sila      | 1     | 950     | 950            | 3 days     |
| Power supply                    | 12V35A CCR        |           | 1     | 2,500   | 2,500          |            |
| Resistor pack                   | custom            | CCR       | 3     | 300     | 900            | 3 days     |
| Circuit box                     | #0                | CCR       | 1     | 400     | 400            | in stock   |
| Circuit box                     | #1                | CCR       | 1     | 450     | 450            | in stock   |
| Relay 24V Koeke                 | MB2               | CCR       | 5     | 150     | 750            | 7 days     |
| Magnetic switch 10A             | H10C              | CCR       | 1     | 550     | 550            | in stock   |
| Pilot lamp                      |                   | CCR       | 2     | 150     | 300            | in stock   |
| Misc hardware & assembly custom |                   | CCR       | 1     | 2,000   | 2,000          | 7 days     |
| <b>DRIVE SYSTEM</b>             |                   |           |       |         |                |            |
| Step motor Step-Syn             | 103-815-2         | Flexible  | 2     | 5,625   | 11,250         | 30 days    |
| Step motor Step-Syn             | 103-8920-26       | Flexible  | 1     | 15,000  | 15,000         | 30 days    |
| Air cylinder 40X1200mm          | SUE               |           | 1     | 4,500   | 4,500          | 30 days    |
| Solenoid valve                  | 183-4E2-13        | Flexible  | 1     | 4,200   | 4,200          | 30 days    |
| Muffler                         | KM-1              | Flexible  | 1     | 402     | 402            | 30 days    |
| Pressure regulator              | RTL6-02           | Flexible  | 1     | 1,060   | 1,060          | 30 days    |
| Speed control                   | ESC6-PT 1/4-0     | Flexible  | 1     | 290     | 290            | 30 days    |
| Hydraulic chuck system          | N-206             | Tzu Sheng | 1     | 121,208 | 121,208        | 30 days    |
| Rotary feeder & hopper          | custom            | Choorat   | 1     | 10,000  | 10,000         | 15 days    |
| <b>LATHE</b>                    |                   |           |       |         |                |            |
| Engine lathe                    | YAM-550           | SUE       | 1     |         |                | 0 in stock |
| Cut off tool post               | custom            | Choorat   | 1     | 2,000   | 2,000          | 7 days     |
| Cut off tool holder             | ENTARN161H33      | SUE       | 1     |         |                | 0 in stock |
| Cut off tool insert             | CUTTER SLIDE      | SUE       | 1     |         | 0              | in stock   |
| Turn tool post                  | custom            | Choorat   | 1     | 2,000   | 2,000          | 7 days     |
| Turn tool holder                | CF3-3             | SUE       | 1     |         | 0              | in stock   |
| Turn tool insert                | TNPA332           | SUE       | 1     |         | 0              | in stock   |
| Stopper tip                     | custom            | Choorat   | 1     | 400     | 400            | 3 days     |
| Switch actuator                 | custom            | Choorat   | 1     | 1,000   | 1,000          | 3 days     |
| Lathe bore adaptor              | custom            | Choorat   | 1     | 1,000   | 1,000          | 3 days     |
| Limit switch and bracket custom |                   | Choorat   | 3     | 700     | 2,100          | 7 days     |
| Motor mount and coupling custom |                   | Choorat   | 3     | 1,000   | 3,000          | 7 days     |
| Feed system bracket             | custom            | Choorat   | 1     | 3,000   | 3,000          | 7 days     |
| User tool kit                   | custom            | CCR       | 1     | 10,000  | 10,000         | 7 days     |
| <b>TOTAL</b>                    |                   |           |       |         | <b>208,700</b> |            |

Appendix E. Vender List.

CCR

หจก. คอมพิวเตอร์ คอนโทร โรบอดิค มาโนช ประพันธ์ ผู้จัดการ  
8/25 หมู่ 3 ถนนสุขุมวิทซอย 3 ตำบลช้างเผือก อ. เมือง เชียงใหม่ 50300  
โทร/แฟกซ์ (053) 217053 มือถือ (01) 9605787

Choorat

ชูรัตน์ ธารารักษ์ สถาบันเทคโนโลยีราชมงคล วิทยาเขตภาคพายัพ  
คณะวิชาเครื่องกล แผนกวิชาช่างกลเกษตร  
128 ถนนห้วยแก้ว อ. เมือง เชียงใหม่ 50000  
โทร. (053) 213112, 213134, 221576 ต่อ 467

Flexible

Flexible Automation System Co. Ltd. สุนทร แซ่ลี Sales Engineer  
263/6 หมู่ 4 ถนนลำพูน - ดอยศรีวิชัย ต. ป่าสัก อ. เมือง ลำพูน 51000  
โทร. (053) 537518-9 แฟกซ์ (053) 537517

SUE

SANYO Universal Electric Public Company Ltd. Compressor Factory  
องอาจ วิชาติยานุกุล Engineer QI Section (IE) 19 สุขุมวิท ซอย 103 กรุงเทพฯ 10260  
โทร. (02) 3980120 ต่อ 388 แฟกซ์ (02) 3980120 ต่อ 261





Sila

บริษัท ศิลาสิริ จำกัด  
1108/41 ศูนย์การค้าพระโขนง ถนนสุขุมวิท กรุงเทพฯ 10110  
โทร. (02) 7122850-2 แฟกซ์ (02) 3811447





Tzu Cheng

บริษัท จือเฉิน (ไทยแลนด์) จำกัด ศักดา พงศาสนองกุล  
7/194 หมู่ 14 บางนา-ตราด กม. 6.5 บางแก้ว-บางพลี สมุทรปราการ 10540  
โทร. (02) 3163960-1, 3160873, 01-3535038 แฟกซ์ (02) 3160873





# Appendix F. Test Result Run 1.







Appendix F. Test Result Run 1 (continue).







Appendix F. Test Result Run 2.







Appendix F. Test Result Run 2 (continue).







Appendix F. Test Result Run 3.







Appendix F. Test Result Run 3 (continue).



Appendix F. Test Result Run 4.





Appendix F. Test Result Run 4 (continue).



**Appendix G. Drawings.**


The technical drawings for the control system and mechanical parts are in the following pages:






CROSS SLIDE MOTOR WIRING

|                                                               |                     |   |  |
|---------------------------------------------------------------|---------------------|---|--|
| Instrumentation and Control Research Laboratory               |                     |   |  |
| Institute for Science and Technology Research and Development |                     |   |  |
| Subject: Single Purpose Lothe                                 | Designed by: Thowan |   |  |
| Project: SUE Production Line                                  | Date: 28 Oct 96     |   |  |
| File: SUE31                                                   | Scale: 1:1          |   |  |
|                                                               | Drawing No.         | 0 |  |





TURN SLIDE MOTOR WIRING

|                                                               |                     |  |  |
|---------------------------------------------------------------|---------------------|--|--|
| Instrumentation and Control Research Laboratory               |                     |  |  |
| Institute for Science and Technology Research and Development |                     |  |  |
| Subject: Single Purpose Lothe                                 | Designed by: Thrawn |  |  |
| Project: SUC Production Line                                  | Date: 26 Oct 96     |  |  |
| File: SUGL32                                                  | Scale: 1:1          |  |  |
|                                                               | Drawing No: 0       |  |  |




STOPPER MOTOR WIRING

|                                                       |  |        |  |
|-------------------------------------------------------|--|--------|--|
| Institute for Science and Control Research Laboratory |  |        |  |
| Subject: Single Purpose Lathe                         |  |        |  |
| Project: SUE Production Line                          |  |        |  |
| File: SUE33                                           |  |        |  |
| Designed by: Thoren                                   |  | Thoren |  |
| Scale: 2:1                                            |  | 2:1    |  |
| Drawing No. 0                                         |  | 0      |  |





POWER CONTROL UNIT


Instrumentation and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 File: SLIDE 42  
 Designed by: Thawan  
 Date: 26 Oct. 96  
 Scale: 1:2  
 Drawing No. 0



12V

POWER CONTROL UNIT






POWER CONTROL UNIT

24V

|                                                               |                     |
|---------------------------------------------------------------|---------------------|
| Instrumentation and Control Research Laboratory               |                     |
| Institute for Science and Technology Research and Development |                     |
| Subject: Single Purpose Lathe                                 | Designed by: Thawan |
| Project: SUE Production Line                                  | Date: 26 Oct 95     |
| File: SLIDE 42                                                | Scale: 1:2          |
|                                                               | Drawing No. 0       |






POWER CONTROL UNIT

R


|                                                               |                     |
|---------------------------------------------------------------|---------------------|
| Instrumentation and Control Research Laboratory               |                     |
| Institute for Science and Technology Research and Development |                     |
| Subject: Single Purpose Lathe                                 | Designed by: Thawon |
| Project: SUE Production Line                                  | Date: 26 Oct. 96    |
| File: SLIDE42                                                 | Scale: 1:2          |
|                                                               | Drawing No: 0       |



POWER CONTROL UNIT

WELLY


|                                                                                                                  |                     |
|------------------------------------------------------------------------------------------------------------------|---------------------|
| Instrumentation and Control Research Laboratory<br>Institute for Science and Technology Research and Development |                     |
| Subject: Single Purpose Lathes                                                                                   | Designed by: Thirum |
| Project: SUE Production Line                                                                                     | Date: 26 Oct '96    |
| File: SLIDE42                                                                                                    | Scale: 1:2          |
|                                                                                                                  | Drawing No. 0       |



11th AND COMMAND SWITCHES

Institute for Science and Control Research Laboratory  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 File: SLIDE 41  
 Designed by: Thowon  
 Date: 20 Dec. 96  
 Scale: 1:2  
 Drawing No: 0


CONTROL UNIT COMPONENT PLACEMENT AND WIRING.



CONTROL UNIT COMPONENT PLACEMENT AND WIRING

TRIM AND COMMAND SWITCHES


Information and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 File: SLIDE 41  
 Designed by: Thomas  
 Date: 20 Dec. 96  
 Scale: 1:2  
 Drawing No. 0



CONTROL UNIT COMPONENT PLACEMENT AND WIRING

IRMA AND COMMAND SWITCHES


Institution and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 File: SLIDE41  
 Designed by: Ithwan  
 Date: 20 Dec. 96  
 Scale: 1:2  
 Drawing No: 0




Instrumentation and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 File: SLIDE 41  
 Designed by: Thawan  
 Date: 20 Dec. 96  
 Scale: 1:2  
 Drawing No. 0

CONTROL UNIT COMPONENT PLACEMENT AND WIRING


CUT OFF MOTOR





Instrumentation and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 Date: 20 Dec. 96  
 Scale: 1:2  
 Drawing No: 0

CONTROL UNIT COMPONENT PLACEMENT AND WIRING



Instrumentation and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: Sub Production Line  
 File: SLIDE 41


CONTROL UNIT COMPONENT PLACEMENT AND WIRING


CPU UNIT

Designed by: Inouen  
 Date: 20 Dec 96  
 Scale: 1:2  
 Drawing No: 0










Instrumentation and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 File: SLIDE41  
 Date: 20 Dec 96  
 Scale: 1:2  
 Drawing No. 0


12 VDC GROUND

CONTROL UNIT COMPONENT PLACEMENT AND WIRING



Instrumentation and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUT Production Line  
 Date: 20 Dec 96  
 Scale: 1:2  
 Drawing No: 0

CONTROL UNIT COMPONENT PLACEMENT AND WIRING




CONTROL UNIT COMPONENT PLACEMENT AND WIRING

2 1/4 XDC


Institution and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SLP Production Line  
 File: SLIDE-11  
 Drawn: No. 0

Designed by: Inwon  
 Date: 20 Dec. 96  
 Scale: 1:2



CONTROL SWITCH SCHEMATIC DIAGRAM


|                                                               |                     |              |   |
|---------------------------------------------------------------|---------------------|--------------|---|
| Instrumentation and Control Research Laboratory               |                     |              |   |
| Institute for Science and Technology Research and Development |                     |              |   |
| Subject: Single Purpose Lathes                                | Designed by: Thawan |              |   |
| Project: SUE Production Line                                  | Date: 15 Jan '97    |              |   |
| File: SUDL40A                                                 | Scale: 1:1          |              |   |
|                                                               |                     | Drawing No.: | 0 |



CONTROL SWITCH

FRONT PANNEL


|                                                               |                     |
|---------------------------------------------------------------|---------------------|
| Instrumentation and Control Research Laboratory               |                     |
| Institute for Science and Technology Research and Development |                     |
| Subject: Single Purpose Lathe                                 | Designed by: Thaeon |
| Project: SUE Production Line                                  | Date: 26 Oct. 98    |
| File: SUE40                                                   | Scale: 1:1          |
|                                                               | Drawing No. 0       |



CONTROL SWITCH

PART LAYOUT

|                                                                                                                  |                      |
|------------------------------------------------------------------------------------------------------------------|----------------------|
| Instrumentation and Control Research Laboratory<br>Institute for Science and Technology Research and Development |                      |
| Subject: Single Purpose Lathe                                                                                    | Designed by: Thomson |
| Project: SUG Production Line                                                                                     | Date: 26 Oct. 96     |
| File: SUG040                                                                                                     | Scale: 1:1           |
|                                                                                                                  | Drawing No. 0        |







CONTROL SWITCH





PCB

|                                                               |                        |             |            |
|---------------------------------------------------------------|------------------------|-------------|------------|
| Instrumentation and Control Research Laboratory               |                        |             |            |
| Institute for Science and Technology Research and Development |                        |             |            |
| Subject                                                       | Single Purpose Lattice | Designed by | Thawan     |
| Project                                                       | Sub Production Line    | Date:       | 26 Oct. 96 |
| File:                                                         | SUDE40                 | Scale:      | 1:1        |
|                                                               |                        | Drawing No. | 0          |





Appendix F. Test Result Run 1 (continue).







Appendix F. Test Result Run 2.







Appendix F. Test Result Run 2 (continue).







Appendix F. Test Result Run 3.







Appendix F. Test Result Run 3 (continue).



Appendix F. Test Result Run 4.




Appendix F. Test Result Run 4 (continue).



**Appendix G. Drawings.**


The technical drawings for the control system and mechanical parts are in the following pages:






CROSS SLIDE MOTOR WIRING

|                                                               |                     |
|---------------------------------------------------------------|---------------------|
| Instrumentation and Control Research Laboratory               |                     |
| Institute for Science and Technology Research and Development |                     |
| Subject: Single Purpose Lath                                  | Designed by: Thawan |
| Project: SUG Production Line                                  | Date: 28 Oct. 96    |
| File: SLIDE31                                                 | Scale: 1:1          |
|                                                               | Drawing No: 0       |





TURN SLIDE MOTOR WIRING

|                                                               |                    |
|---------------------------------------------------------------|--------------------|
| Instrumentation and Control Research Laboratory               |                    |
| Institute for Science and Technology Research and Development |                    |
| Subject: Single Purpose Lathes                                | Designed by: Thurn |
| Project: SUT Production Line                                  | Date: 20 Oct '96   |
| File: SUBE.12                                                 | Scale: 1:1         |
|                                                               | Drawing No: 0      |



STOPPER MOTOR WIRING


|                                                               |                     |  |  |
|---------------------------------------------------------------|---------------------|--|--|
| Instrumentation and Control Research Laboratory               |                     |  |  |
| Institute for Science and Technology Research and Development |                     |  |  |
| Subject: Single Purpose Lathe                                 | Designed by: Thawon |  |  |
| Project: SUE Production Line                                  | Date: 26 Oct '96    |  |  |
| File: SLIDE 33                                                | Scale: 1:1          |  |  |
|                                                               | Drawing No: 0       |  |  |





POWER CONTROL UNIT

Institute for Science and Control Research Laboratory  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 File: SLIDE42

Designed by: Thawon  
 Date: 26 Oct. 96  
 Scale: 1:2  
 Drawing No. 0






POWER CONTROL UNIT

220V

Instrumentation and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUT Production Line  
 File: SUT42


Designed by: Ina-on  
 Date: 26 Oct 96  
 Scale: 1:2  
 Drawing No. 0



POWER CONTROL UNIT

444

|                                                                                                                  |                     |
|------------------------------------------------------------------------------------------------------------------|---------------------|
| Instrumentation and Control Research Laboratory<br>Institute for Science and Technology Research and Development |                     |
| Subject: Single Purpose Lathe                                                                                    | Designed by: Thawon |
| Project: SUE Production Line                                                                                     | Date: 26 Oct 96     |
| File: SLIDE42                                                                                                    | Scale: 1:2          |
|                                                                                                                  | Drawing No. 0       |




POWER CONTROL UNIT

CONTROL


|                                                               |                      |
|---------------------------------------------------------------|----------------------|
| Instrumentation and Control Research Laboratory               |                      |
| Institute for Science and Technology Research and Development |                      |
| Subject                                                       | Single Purpose Lathe |
| Project                                                       | SUE Production Line  |
| File                                                          | SLIDE42              |
| Designed by:                                                  | Thawon               |
| Date                                                          | 26 Oct 96            |
| Scale                                                         | 1:2                  |
| Drawing No                                                    | 0                    |








Instrumentation and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 Date: 20 Dec. 96  
 Scale: 1:2  
 Drawing No: 0




CONTROL UNIT COMPONENT PLACEMENT AND WIRING

Institution and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 File: SLIDE41  
 Designed by: Thawon  
 Date: 20 Dec. 96  
 Scale: 1:2  
 Drawing No. 0



|                                                                                                                  |                                                                                |                                                                        |
|------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|------------------------------------------------------------------------|
| Instrumentation and Control Research Laboratory<br>Institute for Science and Technology Research and Development | Subject: Single Purpose Lathe<br>Project: SUT Production Line<br>File: SLIDE41 | Designed by: Ithwan<br>Date: 20 Dec. 96<br>Scale: 1:2<br>Drawing No. 0 |
|------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|------------------------------------------------------------------------|



CONTROL UNIT COMPONENT PLACEMENT AND WIRING


CUT OFF MOTOR


1000 AND COMMAND SWITCHES

Instrumentation and Control Research Laboratory  
Institute for Science and Technology Research and Development

Subject: Single Purpose Lathe  
Project: SUE Production Line  
File: SLIDE41

Designed by: Inawan  
Date: 20 Dec. 96  
Scale: 1:2  
Drawing No: 0







CONTROL UNIT COMPONENT PLACEMENT AND WIRING

TURN AND COMMAND SWITCHES


Institution and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUE Production Line  
 File: SUE41  
 Designed by: Inowan  
 Date: 20 Dec. 96  
 Scale: 1:2  
 Drawing No: 0












CONTROL UNIT COMPONENT PLACEMENT AND WIRING

IRIM AND COMMAND SWITCHES

Institute for Science and Control Research Laboratory  
Subject: Single Purpose Lathe  
Project: SUE Production Line  
File: SUE41  
Designed by: Inwon  
Date: 20 Dec 96  
Scale: 1:2  
Drawing No: 0






CONTROL UNIT COMPONENT PLACEMENT AND WIRING



24 XDC

Instrumentation and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SUG Production Line  
 File: SLIDE-41  
 Inset: 20 Dec. 96  
 Date: 1.2  
 Score: 0  
 Drawing No: 0



Institution and Control Research Laboratory  
 Institute for Science and Technology Research and Development  
 Subject: Single Purpose Lathe  
 Project: SLE640A  
 Date: 15 Jan '97  
 Scale: 1:1  
 Drawing No: 0


CONTROL SWITCH SCHEMATIC DIAGRAM



CONTROL SWITCH

FRONT PANNEL


|                                                       |                    |
|-------------------------------------------------------|--------------------|
| Institute for Science and Control Research Laboratory |                    |
| Subject: Single Purpose Lathe                         | Designed by: Hemon |
| Project: SUE Production Line                          | Date: 26 Oct. 98   |
| File: SLIDE40                                         | Scale: 1:1         |
|                                                       | Drawing No: 0      |



CONTROL SWITCH

PART LAYOUT

|                                             |                  |
|---------------------------------------------|------------------|
| Institution and Control Research Laboratory |                  |
| Subject: Single Purpose Lathe               |                  |
| Project: SUE Production Line                |                  |
| File: SUE40                                 |                  |
| Designed by: Thevon                         | Date: 26 Oct. 96 |
| Scale: 1:1                                  | Drawing No. 0    |



CONTROL SWITCH

PCB

|                                                               |                      |             |            |
|---------------------------------------------------------------|----------------------|-------------|------------|
| Institute for Science and Technology Research and Development |                      |             |            |
| Subject                                                       | Single Purpose Lathe | Designed by | Thawan     |
| Project                                                       | SUC Production Line  | Date        | 26 Oct. 96 |
| File                                                          | SLIDE40              | Scale       | 1:1        |
|                                                               |                      | Drawing No. | 0          |

โครงการ Transfer Line

TRF 6/3/TRFLINE

## โครงการ Transfer Line TRF 6/3/TRFLINE

### สรุปโครงการ

โครงการ Transfer Line เป็นโครงการปรับปรุงกระบวนการผลิตสไลด์เดอร์ ซึ่งเป็นชิ้นส่วนหนึ่งในคอมเพรสเซอร์ โดยนำเอาสถานีนงานต่างๆ 3 สถานีคือ สถานีเจาะ สถานีลบคม และสถานีคว้านมารวมกันเป็นเครื่องจักรชุดเดียว มีกลไกขนถ่ายชิ้นงานระหว่างสถานีแทนการใช้พนักงานในการสร้างเครื่อง Transfer Line บางส่วนก็ใช้เครื่องจักรเก่าของโรงงานมาปรับปรุงใหม่

ทางด้านการดำเนินงาน บริษัท ชันโยฯ เป็นผู้ออกแบบและจัดสร้างระบบ Transfer Line ทั้งหมด โดยมีสำนักงานเทคโนโลยี สถาบันเทคโนโลยีพระจอมเกล้า เจ้าคุณทหารลาดกระบัง และมหาวิทยาลัยเชียงใหม่เป็นผู้ให้คำปรึกษาในการออกแบบ ผลที่ได้จากโครงการ ช่วยให้ประสิทธิภาพของกระบวนการผลิตสูงขึ้น ใช้เนื้อที่ในการผลิตน้อยลง และลดค่าใช้จ่ายในการผลิตชิ้นงาน

โครงการนี้เป็นการออกแบบ และสร้างเครื่องจักรใหม่ โดยนำวัสดุอุปกรณ์ที่มีอยู่มาสร้างเครื่องต้นแบบ การออกแบบ และสร้างเครื่องต้นแบบไม่ได้ลอกเลียนเครื่องจักรที่มีขายอยู่แล้ว แต่เป็นการออกแบบเครื่องจักรโดยการดัดแปลงกลไกการทำงานของเครื่องจักรในโรงงานในรูปแบบต่างๆ มาประยุกต์ให้เหมาะสมกับแต่ละขั้นตอนของการทำชิ้นงาน เครื่องต้นแบบที่ได้พัฒนาขึ้นมายังจำเป็นต้องแก้ไขปรับปรุงในรายละเอียดเพื่อให้มีความแม่นยำสูงกว่าที่เป็นอยู่ จากนั้นจึงจะเข้าไปทดแทนในสายการผลิตจริง ความลำบากของการสร้างเครื่องต้นแบบคือ การสร้างชิ้นส่วนที่นำมาประกอบต้องใช้ช่างฝีมือที่มีความเชี่ยวชาญมาก แม้กระนั้นผลงานที่ออกมาก็ยังไม่ได้ตามข้อกำหนด ผลจากการค้นคว้าวิจัยได้เพิ่มขีดความสามารถของทีมงานในด้านการออกแบบ และการสร้างเครื่องจักรขึ้นใช้เอง พื้นฐานทางด้านเทคโนโลยีที่ได้จากโครงการนี้เป็นการเริ่มต้นสำหรับการพึ่งตนเองทางด้านเทคโนโลยี SUE ยังจะทำการพัฒนาและปรับปรุงต่อไปให้สามารถทำงานได้สมบูรณ์ยิ่งขึ้น

## บทนำ

โครงการ Transfer Line เป็นการปรับปรุงกระบวนการผลิตชิ้นส่วนสไลด์เตอร์ของคอมเพรสเซอร์ให้มีประสิทธิภาพสูงขึ้น ใช้เนื้อที่ในการผลิตน้อยลง เพิ่มความปลอดภัยในการปฏิบัติงาน และลดค่าใช้จ่ายในการผลิตชิ้นงาน โดยการรวมสถานีงานที่แยกกันอยู่ 3 สถานี มารวมกันอยู่ในเครื่องจักรเพียงเครื่องเดียว และทำงานเป็นแบบอัตโนมัติ

ในการผลิตสไลด์เตอร์มีขั้นตอนการผลิตมากถึง 42 ขั้นตอนด้วยกัน และมี 11 ขั้นตอนที่อยู่ในส่วนของการผลิตด้วยเครื่อง Transfer Line ที่จัดสร้างขึ้น แต่เดิมนั้นต้องใช้เครื่องหลายเครื่องในการผลิตสไลด์เตอร์ แบ่งเป็นเครื่องเจาะ 5 เครื่อง (สถานีที่ 1) เครื่องลบคม 1 เครื่อง (สถานีที่ 2) และเครื่องคว้าน 2 เครื่อง (สถานีที่ 3) ใช้พนักงานในการผลิต 5 คน มีกำลังการผลิตชิ้นงานรวม 2,500 ชิ้น/กะ หลังจากพัฒนาเป็นเครื่อง Transfer Line แล้ว จะกลายเป็นเครื่องจักรเพียงเครื่องเดียว ใช้พนักงานดูแล 1 คน และมีอัตราการผลิตชิ้นงาน 3,500 ชิ้น/กะ

ระบบการผลิตของเครื่อง Transfer Line เป็นระบบทำงานแบบอัตโนมัติทั้งหมด ควบคุมการทำงานด้วย Programmable Logic Controller (PLC) โดยประกอบด้วยส่วนสำคัญต่างๆ 4 ส่วนคือ

- 1) แขนกล (Transfer Arm) ทำหน้าที่ขนถ่ายชิ้นงานระหว่างสถานี
- 2) เครื่องเจาะ (Drilling Machine) ประกอบด้วยหัวเจาะ 6 หัว
- 3) เครื่องลบคม (Chamfering Machine) ประกอบด้วยหัวลบคม 12 หัว
- 4) เครื่องคว้าน (Boring Machine) ประกอบด้วยหัวคว้าน 6 หัว

ในการทำงานของเครื่องจะเป็นการผลิตชิ้นงานครั้งละ 6 ชิ้น โดยเคลื่อนไปตามสถานีต่างๆ ซึ่งมีแขนกลที่ทำงานเป็นแบบอัตโนมัติ ชิ้นงานที่ออกจากเครื่อง TRANSFER LINE จะส่งต่อไปยังกระบวนการอื่นอีก 13 ขั้นตอนก็จะได้สไลด์เตอร์ที่สมบูรณ์


## สารบัญ

|                                                                                                    | หน้า        |
|----------------------------------------------------------------------------------------------------|-------------|
| <b>1. หลักการทำงาน</b>                                                                             | <b>3-4</b>  |
| 1.1 การผลิตชิ้นงานสไลด์เดอร์อย่างสมบูรณ์                                                           | 3-4         |
| 1.2 การผลิตชิ้นงานสไลด์เดอร์ในส่วนของการเจาะ,<br>การลบและการคว้านในปัจจุบัน                        | 3-5         |
| 1.3 การผลิตชิ้นงานสไลด์เดอร์จากเครื่อง TRANSFER LINE                                               | 3-7         |
| 1.4 กระบวนการทำงานของเครื่อง TRANSFER LINE                                                         | 3-9         |
| <b>2. การออกแบบและพัฒนา</b>                                                                        | <b>3-14</b> |
| 2.1 Transfer Arm                                                                                   | 3-15        |
| 2.2 Drilling Machine                                                                               | 3-17        |
| 2.3 Chamfering Machine                                                                             | 3-20        |
| 2.4 Boring Machine                                                                                 | 3-22        |
| <b>3. การติดตั้งและทดสอบการทำงาน</b>                                                               | <b>3-24</b> |
| 3.1 การติดตั้งชุดโครงสร้างและชุดควบคุม                                                             | 3-24        |
| <b>4. ผลการดำเนินโครงการ</b>                                                                       | <b>3-26</b> |
| <b>5. ภาคผนวก</b>                                                                                  |             |
| 5.1 แบบเครื่อง TRANSFER LINE<br>บัญชีแสดง Part ของเครื่อง TRANSFER LINE                            |             |
| 5.2 คู่มือการผลิต สไลด์เดอร์ หัวข้อ การเจาะรู, การลบคมรูเจาะ<br>และการคว้านรูสำหรับใส่เพลาล้อเหียง |             |
| 5.3 แบบระบบควบคุม                                                                                  |             |
| 5.3.1 แบบระบบควบคุมเครื่อง TRANSFER LINE - แบบไฟฟ้า                                                |             |
| 5.3.2 แบบระบบควบคุมเครื่อง TRANSFER LINE - โปรแกรม PLC                                             |             |
| 5.3.3 แบบระบบควบคุมเครื่อง TRANSFER LINE - แบบไฮดรอลิก-นิวเมติก                                    |             |
| 5.4 ผลการตรวจสอบความสามารถของกระบวนการ                                                             |             |
| 5.4.1 ผลการตรวจสอบความสามารถของกระบวนการเจาะ<br>ของเครื่องเจาะที่ใช้ในปัจจุบัน                     |             |
| 5.4.2 ผลการตรวจสอบความสามารถของกระบวนการเจาะ<br>ของเครื่อง TRANSFER LINE                           |             |

## 1. หลักการทำงาน

### 1.1 การผลิตชิ้นงาน สไลด์เดอร์ อย่างสมบูรณ์


กระบวนการผลิตชิ้นส่วนสไลด์เดอร์ของคอมเพรสเซอร์ในตู้เย็นชั้นโย มีทั้งหมด 42 ขั้นตอนด้วยกัน โดยเริ่มจากนำแท่งเหล็กหล่อมาลึงปอกผิว และตัดเป็นชิ้นเล็ก ๆ ตามขนาดที่กำหนด จากนั้นจึงนำมากลึงร่องน้ำมันและโค้งที่หัวท้าย ซึ่งสไลด์เดอร์ที่ได้จะเป็นชิ้นงานที่จะนำไปเข้าสู่ Transfer Line ที่จัดสร้างขึ้น ซึ่งมีการทำงาน 11 ขั้นตอนด้วยกัน เมื่อชิ้นงานออกจากชุด Transfer Line แล้วก็จะเข้ากระบวนการต่าง ๆ อีก 13 ขั้นตอน จะได้สไลด์เดอร์ที่สมบูรณ์ แผนภาพการผลิตชิ้นส่วน Slider ดังแสดงในรูปที่ 1.1



รูปที่ 1.1 แผนภาพแสดงการผลิตสไลด์เดอร์ที่สมบูรณ์

## 1.2 การผลิตชิ้นงาน สไลด์เดอร์ ในส่วนของการเจาะ, การลบคม และการคว้านในปัจจุบัน


กระบวนการทำงานของเครื่องเจาะ เครื่องลบคม และเครื่องคว้าน มีขั้นตอนการทำงานดังรายละเอียดที่แสดงในรูปที่ 1.2



รูปที่ 1.2 แผนภูมิแสดงกระบวนการเจาะรู ลบคม และคว้านรูเจาะชิ้นส่วนสไลด์เดอร์ในปัจจุบัน

ปัญหาในการทำงานของระบบเก่า คือ ปัญหาคุณภาพชิ้นงานไม่ได้ตามมาตรฐาน ซึ่งขนาดรูของชิ้นงานต้องมีความถูกต้องแม่นยำสูงมาก

กระบวนการเจาะรู ลบคมรูเจาะ และคว้านรูเจาะ ในปัจจุบันใช้เครื่องจักร 3 สถานีด้วยกัน คือเครื่องเจาะ (5 เครื่อง) กำลังผลิต 520 ชิ้น/กะ/เครื่อง เครื่องลบคม (1 เครื่อง) กำลังการผลิต 3,000 ชิ้น/กะ/เครื่อง และเครื่องคว้านรูเจาะ (2 เครื่อง) กำลังการผลิต 1,250 ชิ้น/กะ/เครื่อง การทำงานเป็นแบบ Manual ใช้ Operator ทั้งหมดจับชิ้นงานเข้าและออกจาก Jig ของเครื่องจำนวน 5 คน โดยการทำงาน 2 กะ ซึ่งกระบวนการ 3 ขั้นตอนนี้ทำให้เกิดของเสียจากการผลิตคิดเป็น 50% ของจำนวนของเสียในสายการผลิตสไลด์เตอร์ทั้งสายการผลิต ซึ่งมีของเสียอยู่ประมาณ 2% แนวทางในการแก้ไขคือ การพัฒนาเครื่องจักรให้มีความแม่นยำสูงเพื่อเพิ่มประสิทธิภาพการผลิตของระบบโดยรวม กระบวนการทำงานของเครื่องจักรที่พัฒนาขึ้นใหม่นี้ประกอบด้วย การเจาะ การลบคม และการคว้านอัดโน้มติ ดังแสดงในรูปที่ 1.3



รูปที่ 1.3 แผนภูมิแสดงกระบวนการเจาะรู ลบคมรูเจาะ และคว้านรูเจาะชิ้นส่วนสไลด์เตอร์ ในระบบ Transfer Line ที่วิจัยและจัดสร้างขึ้น

### 1.3 การผลิตชิ้นงานสไลด์เดอร์จากเครื่อง TRANSFER LINE

จากการที่บริษัท ชันโย ยูนิเวอร์แซล อิเล็กทริก มีความต้องการขยายกำลังการผลิต จึงจำเป็นต้องเพิ่มประสิทธิภาพในการทำงานของเครื่องจักร ดังนั้นจึงได้คิดริเริ่มในการวิจัยเครื่องจักรที่เป็นระบบอัตโนมัติสมบูรณ์แบบขึ้นเป็นระบบ Transfer Line ซึ่งมีกำลังการผลิตประมาณ 3,500 ชิ้น/กะ

การทำงานของชุด Transfer Line ที่ได้ออกแบบขึ้นมาใหม่นี้เป็นการทำงานแบบอัตโนมัติที่สมบูรณ์แบบ ทั้งการทำงานของแต่ละสถานีและการขนย้ายชิ้นงานระหว่างสถานีการทำงาน

ชิ้นงานที่ Stocker จะถูกมือจับ ของชุดขนย้ายชิ้นงาน (Transfer Arm) จับชิ้นงานมาไว้ที่ตำแหน่งเจาะที่ละ 6 ชิ้นงาน แล้วเริ่มทำการเจาะ มือจับที่ประกอบอยู่กับรางเลื่อนที่อยู่ด้านบนของชุดเครื่องจักรจะทำการจับชิ้นงานแล้วเคลื่อนย้ายชิ้นงานจากตำแหน่งของชุดเจาะไปยังชุดลบคมชิ้นงาน


หลังจากกระบวนการเจาะเสร็จสิ้นลง มือจับจะจับและย้ายชิ้นงานจากตำแหน่งเจาะไปยังตำแหน่งลบคม พร้อมกับหยิบชิ้นงานใหม่เข้ามาที่ตำแหน่งเจาะด้วย ชุดหัวลบคมมี 2 ชุด ในการลบคม หัวลบคมจะเคลื่อนที่เข้าไปหาชิ้นงานทั้ง 2 ด้านของรู เพื่อลบคมที่เกิดจากการเจาะ

เมื่อชิ้นงานผ่านกระบวนการลบคมแล้ว มือจับจะเคลื่อนที่ไปจับชิ้นงานเพื่อเคลื่อนย้ายไปยังตำแหน่งคว้าน จังหวะนี้มือจับอีกชุดก็จะจับชิ้นงานจากชุดเจาะมาที่ Jig ของชุดลบคมพร้อม ๆ กันไปด้วย

การทำงานทั้งหมดเป็นการทำงานในลักษณะต่อเนื่อง โดยมีการควบคุมจากเครื่อง PLC ในลักษณะของ Open Loop Mode

ส่วนขั้นตอนการทำงานของเครื่อง TRANSFER LINE แสดงในรูปที่ 1.4

## ขั้นตอนการทำงานของเครื่อง Transfer Line



รูปที่ 1.4 แสดงขั้นตอนการทำงานของเครื่อง Transfer Line

#### 1.4 กระบวนการทำงานของเครื่อง TRANSFER LINE

ก. กระบวนการป้อนชิ้นงานเข้าสู่เครื่อง Transfer Line

วัตถุประสงค์ :

เพื่อทำการป้อนชิ้นงานสไลด์เดอร์ครั้งละ 6 ชิ้นเข้าสู่กระบวนการเจาะ

กระบวนการ :

ชิ้นงานสไลด์เดอร์ที่บรรจุอยู่ภายใน STOCKER ทั้ง 6 ชุด เป็นชิ้นงานที่พร้อมเข้าสู่กระบวนการผลิต ลักษณะของ STOCKER เป็นแมกกาซีนในแนวตั้ง มีมุมเอียงประมาณ 15 องศา เพื่อให้ชิ้นงานสไลด์เดอร์เคลื่อนที่ออกจากแมกกาซีนได้ ชิ้นงานสไลด์เดอร์ที่จะถูกลำเลียงออกมาในแนวนอน ซึ่งสายลำเลียงจะมีทั้งหมด 6 สายการลำเลียง และชิ้นงานสไลด์เดอร์ทั้ง 6 ชิ้นจากสายลำเลียง จะถูกจับด้วยมือจับทั้ง 6 ชุดของ Transfer Arm ตำแหน่งที่ชิ้นงานสไลด์เดอร์ถูกจับคือบริเวณหัว-ท้ายของชิ้นงาน เพื่อเข้าสู่กระบวนการเจาะ (Drilling) ในขั้นตอนต่อไป ลักษณะของชิ้นงานสไลด์เดอร์เป็นเหล็กหล่อตันทรงกระบอกขนาดเส้นผ่าศูนย์กลาง 21.3 mm ความยาว 25 mm.



รูปที่ 1.5 แสดงชุด STOCKER